

FILED

Date: 7-19-2018 By: SC

This survey consists of:

Map: _____

Narrative: _____

Corner Rpt: CS 65/101-36

DOUGLAS COUNTY
SURVEYOR

CORNER REPORT FORM

Section 4 Township 32S Range 5W
Douglas County Date 5-2018
PLSS Number 340640

CORNER DESIGNATION

C 1/4

- Condition Report only
- Not Found
- Renewed
- Unrecorded
- Surveyed In
- Referenced out


Previous Renewals/Surveys, etc:
M 106-50 Johnstone 1988

Monument(s) & Accessories Found: (Condition and Source)

5/8" I. Rod with Alum CAP
22" FIR N29°W 15° FT GOOD SCAR
3B" FIR S48°E 28° FT GOOD SCAR

Monument Detail

Sketch



Monument Set (Procedures and Description)

New Accessories

4" FIR N70°E 14° FT Scribed C 1/4 S 4 RT
10" FIR S2°E 9° FT " " " "

Location & Comments

Compass Declination 15 1/2°
Firm/Agency: i.e. Engineering, Inc.
Address: 809 SE Pine St., Roseburg, OR 97470
Party Chief:
Notes:
Witness:

Surveyor's Seal

REGISTERED
PROFESSIONAL
LAND SURVEYOR

Ronald A. Gimby
OREGON
JULY 14, 1978
RONALD A. GIMBY
1654

EXP 12-31-18

C.S. File 65/101-36