

FILED

Date: 7-18-2018 By: SC
This survey consists of:

Map: _____

Narrative: _____

Corner Rpt: CS 65/101-42

DOUGLAS COUNTY
SURVEYOR

CORNER REPORT FORM

Section 8, 17 Township 31S Range 6W
Douglas County Date 01/15/2018
PLSS Number 240500

CORNER DESIGNATION

1/4 S8
S17

- Condition Report only
- Not Found
- Renewed
- Unrecorded
- Surveyed In
- Referenced out

Previous Renewals/Surveys, etc:

Sept 1964, Douglas County Surveyors Office Renewal
Sept 2003, Estabrook Renewal (CS65/48-29)

Monument(s) & Accessories Found: (Condition and Source)

Found 2-1/2" brass cap on 1" iron pipe from which a:
21" Madrone snag bears N18°E 11.2'
10" (now 13") D. fir with healed face bears N77°E 22.1' to spike @ center.
10" (now 11") D. fir with healed face bears N11°E 26.2' to spike @ center.
5/8" iron rod with aluminum cap marked "BO1" bears N47°W 6.3'
5/8" iron rod with aluminum cap marked "BO2" bears N44°E 7.7'

Monument Detail

Sketch



Monument Set (Procedures and Description)


New Accessories

Surveyor's Seal


Location & Comments

OREGON COORDINATE
REFERENCE
SYSTEM, COTTAGE GROVE -
CANYONVILLE ZONE, NAD 88-
(2011),
EPOCH 2010 PER GPS
OBSERVATION
HOLDING NGS CORS STATIONS
"RSBG" & "DDSN"

Compass Declination 15°
Firm/Agency: Land Mark Surveying, Inc.
Address: P.O. Box 13
Roseburg, OR 97470
Party Chief: Bartt Heichel
Notes: _____
Witness: Anthony Welch



Mark A. Heimbürger



Renews 6/30/19

CS File 65/101-42