

FILED

Date: 7/18/2018 By: SC

This survey consists of:

Map: _____

Narrative: _____

Corner Rpt: CS 65/101-44

DOUGLAS COUNTY
SURVEYOR

CORNER REPORT FORM

Section 2 Township 32S Range 7W
Douglas County Date 02/27/2018
PLSS Number _____

CORNER DESIGNATION

T31S, R7W
S35
S2
T32S, R7W

- ___ Condition Report only
- ___ Not Found
- X Renewed
- ___ Unrecorded
- ___ Surveyed In
- ___ Referenced out

Previous Renewals/Surveys, etc:

Oct. 1963/June 1964 BLM renewal

Monument(s) & Accessories Found: (Condition and Source)

Found 2-1/2" iron pipe with 2-1/2" brass cap from which a:

- Rooted Live Oak Stump with no visible face bears S55°E 10.6'
- 16" D. fir (now 17" stump) with healed face bears S5°W 44.9'
- 45" (now 48") D. fir with healed face bears N10°W 31.7'
- 19" D. fir (now 20" wind fall) with healed face bears N45°E 25.0'

Monument Detail

Sketch



Monument Set (Procedures and Description)

New Accessories

- 12" Live Oak scribed "1/4 S2 BT" bears S60°E 10.6'
- 4" D. fir scribed "X BT" bears S5°E 10.5'
- 28" D. fir scribed "1/4 S35 BT" bears N61°W 43.0'

Surveyor's Seal

Location & Comments

OREGON COORDINATE
REFERENCE
SYSTEM, COTTAGE GROVE -
CANYONVILLE ZONE, NAD 88-
(2011),
EPOCH 2010 PER GPS
OBSERVATION
HOLDING NGS CORS
STATIONS "BERG" & "DDCN"

Compass Declination 16°
Firm/Agency: Land Mark Surveying, Inc.
Address: P.O. Box 13
Roseburg, OR 97470
Party Chief: Bartt Heichel
Notes: _____
Witness: Anthony Welch



Renews 6-30-19

CS File 65/101-44