

OREGON CORNER RESTORATION FORM

Section 4 Township 22 South, Range 9 West
County Douglas Date 24 September 2018

FILED
Date: 4-9-2019 By: JC
This survey consists of:
Map: _____
Narrative: _____
Corner Rpt: CS 65/102-B
DOUGLAS COUNTY
SURVEYOR

Corner Description

N1/16

___ Condition Report Only

Section 4

- ___ Not Found
- X Renewed
- ___ Unrecorded
- ___ Surveyed In
- ___ Referenced Out

Previous Renewals / Surveys, etc.

Monument (s) & Accessories Found: (Condition and Source)

Found 3-1/4" BLM brass cap on iron pipe, dated 1987
9" X 4' D. Fir stump with healed face bears S 42-1/2° W 26.7'
Record D. Fir bearing N 2° W – not found

Monument Detail

Sketch

Monument Set (Procedures and Description)

None

New Accessories

20" Maple bears N 8° E 39.6 ft. blazed, scribed, X BT
13" Maple bears N 72° W 28.6' blazed, scribed N1/16 S4 BT

Location & Comments

Corner has steel post _____ Compass Declination 16° East
 adjacent to it. _____ Firm/Agency Northwest Land
All BT's have red painted _____ Surveying Inc.
bands and yellow tags. _____ Address P.O. Box 2827
 _____ Florence, OR 97439
 _____ Party Chief Ron Rice
 _____ Notes _____
 _____ Witness _____

Surveyor's Seal



RENEWS: 12-31-2018

400660

C.S. FILE 65/102-B