

FILED

Date: 4/16/2019 By: SC

This survey consists of:

Map: \_\_\_\_\_

Narrative: \_\_\_\_\_

Corner Rpt: CS 65/102-20

DOUGLAS COUNTY  
SURVEYOR

**OREGON CORNER RESTORATION FORM**

**SECTION 7 & 18      TOWNSHIP 22S      RANGE 11W, WM**

**Corner Designation**


1/4 CORNER SECTIONS 7 & 18

**Previous Renewals / Surveys, etc.:**

M1-54, M65-4 & M147-32

- \_\_\_ Condition Report Only
- \_\_\_ Not Found
- Renewed
- \_\_\_ Unrecorded
- \_\_\_ Surveyed in
- \_\_\_ Referenced Out

**Monument Detail Sketch**



**Monument Found or Set (Procedures and Description)**

**FOUND MONUMENT:**

A 1/2" IRON PIPE PER M1-54 WITH 2 1/2" BRASS CAP MARKED "T22S R11W 1/4 S7 S18 LS 845", UNKNOWN RECORD.

**FOUND BT'S:**

A 17" MYRTLE WITH VISIBLE BARK SCRIBE AND TAG BEARS S25°E 20.0'.

A 24" FIR WIND FALL BEARS S05°E 25.3'.

A ROTTEN ALDER STUMP BEARS N04°W 14.1'.

**New Accessories**

**NEW BT MARKED:**

A 30" HEMLOCK, FACE SCRIBED "N1/4 S18 BT" WITH X-CHOP AND TAG BEARS S63°W 12.5' TO A SPIKE AT SIDE CENTER.

**Locations & Comments**

LAT. AND LONG. PER GARMIN ETREX HAND HELD GPS

N: 43°39'45.9"    W: 124°03'33.5"

DATE 10/3/18

**Compass Declination 18° EAST**

**Firm / Agency: Estabrook Land Surveying Inc.**

**Address: PO BOX 574, Lakeside, OR 97449**

**Party Chief: Pat Coy**

**Notes:**

**Witness: John Rondeau**

**Surveyors Seal**

REGISTERED  
PROFESSIONAL  
LAND SURVEYOR

OREGON  
JUNE 30, 1995  
JERRY LEE ESTABROOK  
2703

EXPIRES 12/31/19

C.S. FILE 65/102-20