

FILED

Date: 4/14/2019 By: JC

This survey consists of:

Map: _____

Narrative: _____

Corner Rpt: CS 65/102-21

OREGON CORNER RESTORATION FORM

SECTION 18

TOWNSHIP 22S

RANGE 11W, WM

DOUGLAS COUNTY
SURVEYOR

Corner Designation


CN1/16 CORNER SECTION 18

Previous Renewals / Surveys, etc.:

M65-4

- ___ Condition Report Only
- ___ Not Found
- Renewed
- ___ Unrecorded
- ___ Surveyed in
- ___ Referenced Out

Monument Detail Sketch



Monument Found or Set (Procedures and Description)

FOUND MONUMENT:

A 3/4" IRON PIPE WITH 3" BRASS CAP MARKED "T22S R11W C N1/16 C S18 1977 PLS 1091" ATTACHED TO IRON SHAFT IN A 42" FIR STUMP, PER M65-4.

FOUND BT'S:

- A 20" ALDER SNAG WITH ROTTEN FACE AND TAG BEARS S12°W 11.6'.
- A 16" ALDER WITH HEALED FACE AND TAG BEARS N68°30'W 25.6'.

New Accessories

NEW BT MARKED:

A 17" FIR, FACE SCRIBED "CN1/16 S18 BT" WITH X-CHOP AND TAG BEARS S16°E 44.6' TO A SPIKE AT SIDE CENTER.

Locations & Comments

LAT. AND LONG. PER GARMIN ETREX HAND HELD GPS
N: 43°39'33.8" W: 124°03'35.5"

DATE 10/3/18

Compass Declination 18° EAST
 Firm / Agency: Estabrook Land Surveying Inc.
 Address: PO BOX 574, Lakeside, OR 97449
 Party Chief: Pat Coy
 Notes:
 Witness: John Rondeau

Surveyors Seal

REGISTERED
 PROFESSIONAL
 LAND SURVEYOR

OREGON
 JUNE 30, 1985
 JERRY LEE ESTABROOK
 2703

EXPIRES 12/31/19

C.S. FILE 65/102-21