

FILED

Date: 7/9/2019 By: JLC

This survey consists of:

Map: _____

Narrative: _____

Corner Rpt: CS 65/102-63

OREGON CORNER RESTORATION FORM

SECTION 4 TOWNSHIP 22S RANGE 11W, WM

DOUGLAS COUNTY SURVEYOR

Corner Designation


CW1/16 CORNER SECTION 4

Previous Renewals / Surveys, etc.:

DCSO RECORDS VOL. 53 PAGE 20230

- Condition Report Only
- Not Found
- Renewed
- Unrecorded
- Surveyed in
- Referenced Out

Monument Detail Sketch



Monument Found or Set (Procedures and Description)

FOUND MONUMENT:

A 3 1/4" BRASS TABLET MARKED "C W1/16 C S4 1992" IN SOLID ROCK, PER DCSO RECORDS VOL. 53 PAGE 20230.

FOUND BT'S:

A 56" CEDAR STUMP WITH VISIBLE SCRIBE AND TAG BEARS N19°15'W 50.49'.

New Accessories

NEW BT'S MARKED:

AN 11" ALDER, BARK SCRIBED "CW1/16 S4 BT" WITH X-CHOP AND TAG BEARS S67°W 25.00' TO A SPIKE AT SIDE CENTER.

AN 8" ALDER, BARK SCRIBED "CW1/16 S4 BT" WITH X-CHOP AND TAG BEARS N52°W 7.80' TO A SPIKE AT SIDE CENTER.

NOTE: THE CORNER FALLS 13.2' EAST OF RAVINE THAT DRAINS N20°W.

Locations & Comments

LAT. AND LONG. PER GARMIN ETREX HAND HELD GPS
N: 43°41'06.4" W: 124°01'29.3"

DATE 5/24/19

Compass Declination used on hand compass 18° EAST

Firm / Agency: Estabrook Land Surveying Inc.

Address: PO BOX 574, Lakeside, OR 97449

Party Chief: Pat Coy

Notes:

Witness: John Rondeau and Ray Banks

Surveyors Seal

REGISTERED PROFESSIONAL LAND SURVEYOR

OREGON
JUNE 30, 1995
JERRY LEE ESTABROOK
2703

EXPIRES 12/31/19

320640

C.S. FILE 65/102-63