

FILED

Date: 12-16-19 By: DA

This survey consists of:

Map: CS 65/103-014

Narrative: _____

Corner Rpt: _____

DOUGLAS COUNTY
SURVEYOR

S.W. PINE AVENUE
R/W 60'
N28° 00' 26"W 262.59'
(N29° 54' 35"W 262.57')

S.W. 4TH STREET
R/W 60'

S68° 01' 50"E 39.03'

FD. SPIKE (RR SPIKE)
PER M32-15 DESTROYED
DURING CONSTRUCTION

FOUND 5/8" IRON
ROD PER M76-71

LEGEND

- ⊙ FD. 5/8" IRON ROD PER M32-15 UNLESS NOTED
- SET 5/8"x30" IRON ROD W/ CAP MARKED "LAND MARK SURVEYING, INC. IN UTILITY VALVE BOX W/ CAST IRON LID

RECORD INFORMATION

() M32-15

NARRATIVE:

THE PURPOSE OF THE SURVEY IS TO RECORD RESTORATION OF A MONUMENT DESTROYED DURING CONSTRUCTION.

THE ORIGINAL LOCATION WAS TIED AND REFERENCED AND THE MONUMENT REPLACED IN THE ORIGINAL HORIZONTAL LOCATION.

BASIS OF SURVEY - OREGON COORDINATE SYSTEM- SOUTH ZONE (NAD 83 (2011) , EPOCH 2010) PER SW PINE AVE. STREET IMPROVEMENTS PLANS BY THE DYER PARTNERSHIP ENGINEERS & PLANNERS, INC.

REGISTERED
PROFESSIONAL
LAND SURVEYOR

Mark Heimbarger

OREGON
JULY 16, 1987
MARK A. HEIMBURGER
2287

RENEWS JUNE 30, 2021

MONUMENT RESTORATION

In NW 1/4, Sec. 34
T. 30 S., R. 5 W., W.M.
City of Canyonville, Douglas County, Oregon
NOV. 20, 2019

FOR: KNIFE RIVER MATERIALS
P.O. BOX
ROSEBURG, OR 97470

LM Proj. No. 2019-0066

Land Mark
SURVEYING INC.
3329 N.E. Stephens Street
Roseburg, Oregon 97470
Tel (541) 677-9400
Fax (541) 677-9401

Sheet 1 of 1

C.S. FILE 65/103-014



SCALE: 1" = 20'