

FILED

Date: 2/11/2020 By: SC

This survey consists of:

Map: _____

Narrative: _____
Corner Rpt: CS 65/104-33

DOUGLAS COUNTY
SURVEYOR

CORNER REPORT FORM

Section 14 Township 21S Range 9W
Douglas County Date 1-2020
PLSS Number 400400

CORNER DESIGNATION

SEE COR 16/15
21/22

- Condition Report only
- Not Found
- Renewed
- Unrecorded
- Surveyed In
- Referenced out

Previous Renewals/Surveys, etc:

BLM RESURVEY 1966 Vol 34 Pg. 14242-3
Les Roberts 1983 M 94-4

Monument(s) & Accessories Found: (Condition and Source)

BLM BRASS CAP

27" FIR N74°W 7¹/₂ FT GOOD SCAR NO RECORD

26" CEDAR N2W 53¹/₂ FT GOOD SCAR NO RECORD

These trees were done after M-94-4 was done

Monument Detail

Sketch

US CADASTRAL SURVEY
PENALTY \$250 FOR REMOVAL
T21S R9W
S16/S15
S21/S22
1943

BUREAU OF LAND MANAGEMENT

Monument Set (Procedures and Description)

New Accessories

10" FIR S26°E 16³/₄ FT SCRIBED T21S R9W S22 BT
9" FIR N86°E 27¹/₂ FT SCRIBED T21S R9W S15 BT

Surveyor's Seal



Location & Comments

Compass Declination 15¹/₂°E
Firm/Agency: i.e. Engineering, Inc.
Address: 809 SE Pine St., Roseburg, OR 97470

Party Chief: N. FROMPAHL

Notes:

Witness: J. OGDEN



EXP 12-31-20
C.S. File 65/104-33