

FILED

Date: 7-27-2020 By: SC

This survey consists of:

Map: _____

Narrative: _____

Corner Rpt: CS65/106-40

DOUGLAS COUNTY
SURVEYOR

CORNER REPORT FORM

Section 26 Township 29 S Range 8 W
Douglas County Date 7/24/2020
PLSS Number 540200

CORNER DESIGNATION

South 1/4 Corner

- ___ Condition Report only
- ___ Not Found
- Renewed
- ___ Unrecorded
- ___ Surveyed In
- ___ Referenced out

Previous Renewals/Surveys, etc:

Original G.L.O. in 1855. BLM Resurvey in 1975. Found on M 127-38 and M 142-6.

Monument(s) & Accessories Found: (Condition and Source)

Standard BLM brass capped iron pipe.

1975 BLM BT's found:

A 14" diam., 7' tall Fir stump (very rotted) bears N 10 $\frac{1}{2}$ ^o W, 27.4 feet.

An 18" diam. Fir bears S 42 $\frac{1}{4}$ ^o E, 12.5 feet.

Both have healed blazes.

Monument Detail

Sketch

Standard BLM brass capped iron pipe.

Monument Set (Procedures and Description)

N/A

New Accessories

An 11" diam. Fir scribed "1/4 S26 BT" bears N 9^o E, 24.9 feet.

A six foot steel post is set 2 feet West.

Surveyor's Seal

Location & Comments

Compass Declination 15^o East

Firm/Agency: David Edwards Land Surveying

Address: P.O. Box 361

Oakland, Oregon 97462

Party Chief: Brant Miller

Notes: _____

Witness: Eric Sprinkle

REGISTERED
PROFESSIONAL
LAND SURVEYOR

David A. Edwards

OREGON
JULY 26, 1988
DAVID A. EDWARDS
2339

Renews 12/31/21

C.S. File 65/106-40