

FILED

Date: 10-20-1998 By: JC

GOVERNMENT CORNER RESTORATION FORM

T 29

Township 29S Range 9W Sec. 30 County DOUGLAS Map: _____

State OR Date 10-15-98 No. _____ Narrative: _____

Corner Rpt: 66/4-5

Corner Designation

DOUGLAS COUNTY SURVEYOR

Condition Report Only

Not Found

Renewed

Unrecorded

Surveyed In

Referenced Out

$\frac{1}{4} \frac{S30}{S31}$

Previous Renewals 1965 BLM

MONUMENT DETAIL

Monument(s) Found: (Condition and Source)

3/4" DIA BRASS CAPON A 2 1/2"
OLD IRON PIPE, PROTRUDES
3" ABOVE GROUND, 1965

U.S. DEPT. OF THE INTERIOR
T29S 9W

$\frac{1}{4} \frac{S30}{S31}$

1965
BUR. OF LAND MANAGEMENT

Accessories Found:

14" NOW 30" DIA D. FIR WITH A FULLY HEALED BLAZE
BEARS N14 1/2° E, 42.9 FT (AGREES WITH REC.) 1965

9" NOW 13" DIA. W. OAK WITH A FULLY HEALED BLAZE
BEARS S45 1/2° W, 71.9 FT (AGREES WITH REC.) 1965

C.S. File No. 66/4-5

