

GOVERNMENT CORNER RESTORATION FORM

Date: 4-23-1999 By: JC

This survey consists of:

Township 27S Range 7W Sec. 30 County DOUGLAS

Map: _____

State OR Date 1-26-1999

No. 140200.012

Corner Ppt: 66/8-9

Corner Designation

DOUGLAS COUNTY SURVEYOR

1/4 S30 |
S31

- Condition Report Only
- Not Found
- Renewed
- Unrecorded
- Surveyed In
- Referenced Out

MONUMENT DETAIL

Previous Renewals 1930 + 1958 DC SO

Monument(s) Found: (Condition and Source)

2 1/2" DIA BRASS CAP ON A
1 1/2" DIA IRON PIPE, PROTRUDING
4" ABOVE GROUND, 1958

COUNTY SURVEYORS
T 27S

1/4 S30
S31
R7W
1958
OFFICE

Accessories Found:

NO OBTS FOUND

12" NOW 18" DIA WIDAK WITH A FULLY HEALED
BLAZK BEARS S85/20E, 135.0 FT / C REC.
S84E, 135.0 FT) NOTE 1 BT IS DOUBLE TRUNKED
BRG + DIST TAKEN TO EASTERN TRUNK 1930

1930 SW BT NOT FOUND

14" CEDAR NOW SCATTERED ROTTEN CEDAR
REMAINS WITH ILLEGIBLE SCRIBING FOUND
NEARS RECORD "S46W 91.3 FT" 1958

