

GOVERNMENT CORNER RESTORATION FORM

Date: 4-23-1999 By: SC

Township 30S Range 4W Sec. 25 County DOUGLAS Map:

This survey consists of:

State OR Date 3-1-99

No. 700240.034

Narrative:

Corner Rpt: 66/8-17

Corner Designation

E 1/4
S 25
ONLY

DOUGLAS COUNTY
SURVEYOR

- Condition Report Only
- Not Found
- Renewed
- Unrecorded
- Surveyed In
- Referenced Out

Previous Renewals 1930

Monument(s) Found: (Condition and Source)

NONE FOUND

N/A

Accessories Found:

NW FIR FROM 1930 NOT FOUND

8" NOW 16" DIA. W. OAK WE OPEN AND
FIND OLD AXE MARKS OF A PREVIOUS
SEARCH AND GOOD PARTIAL SCRIBING FOUND
DISTANCE WAS GIVEN TO THIS BT IN
RENEWAL RECORDS ONLY A BEARING
OF S45°W

RENEWAL

Monument Set (Procedure and Description)

Monument Detail

NONE

UNABLE TO DETERMINE A CORNER POSITION, WE PLOTTED POSITION OF FOUND 1930 SW BT BY REFERENCE TO TWO MONUMENTS FROM 1930 (M1-37)

N/A

New Accessories

1/2" DIA IRON BAR FROM 1930 BEARS N 9 1/2° E, 536.6 FT 6" BELOW GROUND.

1" SHAFT WITH 6" DIA CAM FROM 1930 BEARS N 43° E, 716.1 FT 1" BELOW GROUND.

Sketch of Monument, Accessories, and General Area

Location & Comments

COMPASS BEARINGS

1/2" 1930 IRON BAR N 9 1/2° E 536.6 MEAS. 398.85 (N 88° 23' W 384.7) REC 1930

NOTE ERROR IN DIST. ON 1930 SURVEY

1930 1" SHAFT 6" CAM N 43° E 716.1

NOTE: THIS MONUMENT DOES NOT APPEAR TO BE ON THE SECTION LINE

1930 1/6" W. OAK



Comp. Declin. 17 3/4° E Agency DCSD Party Chief RANDALL W. SMITH Notekeeper JAMES G. SMITH Witnesses STEPHEN J. HARRIS

Address

Surveyor's Seal

REGISTERED PROFESSIONAL LAND SURVEYOR

JAMES G. SMITH LICENSE 6-30-2000

OREGON JULY 25, 1990 RANDALL W. SMITH 2489