

GOVERNMENT CORNER RESTORATION FORM

Date: 11-3-1999 By: JC

This survey consists of: _____

Township 26S Range 4W Sec. _____

County DOUGLAS Map: _____

State OR Date 5-24-99

No. 045020.008 Corner Rpt: 66/12-19

Corner Designation

NW
DLC 45

DOUGLAS COUNTY
SURVEYOR

Condition Report Only

Not Found

Renewed

Unrecorded

Surveyed In

Referenced Out

MONUMENT DETAIL

Previous Renewals 1919 + 1959 DCSO

Monument(s) Found: (Condition and Source)

2 1/2" BRASS CAP ON A 1 1/2"
O.D. IRON PIPE, PROTRUDES
14" ABOVE GROUND 1959

COUNTY SURVEYORS OFFICE

T26S R4W

NW COR
DLC 45
1959

Accessories Found:

13" NOW 21" DIA W/ OAK WITH A FULLY HEALED
DOUBLE BLAZES, BLAZES N70°W 51.8 FT
(AGREES WITH REC.) 1959

NO OTHER BT'S FOUND

