

FILED

GOVERNMENT CORNER RESTORATION FORM

Date: 11-17-1999 By: SC

Township 26S Range 3W Sec. 3

County DOUGLAS

This survey consists of:

State OK

Date 8-25-99

No. 400640.011

Map: _____

Narrative: _____

Corner Fpt: 66/12-39

Corner Designation

1/4 S4/S3

DOUGLAS COUNTY

Condition Report Only

Not Found

Renewed

Unrecorded

Surveyed In

Referenced Out

Previous Renewals 1966 DC SO

Monument(s) Found: (Condition and Source)

2 1/2" DIA BRASS CAP ON A
1 1/2" O.D. IRON PIPE PROTRUDES
12" ABOVE GROUND, 1966

COUNTY SURVEYORS OFFICE
T26S

1/4 S4/S3
R3W
1966

Accessories Found:

27" NOW 41" DIA CEDAR WITH A FULLY HEALED
BLAZE, BEARS S21 1/2° W, 37.3 FT (AGREES WITH
8-95 BLM BT TAG) 1966

20" NOW 28" DIA CEDAR WITH A FULLY HEALED
BLAZE, BEARS S42° E, 21.9 FT (AGREES WITH
1966 REC.) 1966

C.S. File No. 66/12-39

C

