

FILED

GOVERNMENT CORNER RESTORATION FORM

Date: 1-6-2000 By: JC

Township 26S Range 3W Sec. 28
11-4-99
State OR Date 7-29-99

County DOUGLAS This survey consists of:

No. 3A0200.011

Map: _____

Narrative: _____

Corner Rpt: 66/13-10

Corner Designation

$\frac{1}{4} \frac{528}{533}$

Condition Report Only
Not Found DOUGLAS COUNTY SURVEYORS

Renewed

Unrecorded

Surveyed In

Referenced Out

Previous Renewals 1966 DCSSO

Monument(s) Found: (Condition and Source)

2 1/2" BRASS CAP ON A 1 1/2"
O.P. IRON PIPE PROTRUDES
8" ABOVE GROUND. 1966

COUNTY SURVEYORS OFFICE

T 26S

S 28

$\frac{1}{4} \frac{533}{533}$

R 3W

1966

Accessories Found:

8" NOW 17" DIA J. CEDAR WITH A FULLY HEALED BLAZE
BEARS N 33° W, 151.0 FT (AGREES WITH REC.)
1966

10" NOW 20" DIA 2 FT HIGH D. FIR STUMP WITH A
FULLY HEALED BLAZE, BEARS S 15° W, 80.0 FT
(AGREES WITH REC.) 1966

6" NOW 16" DIA. DEAD W. OAK WITH A PREVIOUSLY
OPENED ROTTEN BLAZE, NO SCRIBING VISIBLE
BEARS S 15° W, 152.5 FT (AGREES WITH REC.) OBT

C.S. File No. 66/13-10

