

RENEWAL

Monument Set (Procedure and Description)

2 3/8" DIA BRASS CAP ON 1 3/8" O.D.
BY 32" LONG IRON PIPE, IS SET
AT A POSITION DETERMINED BY
ORIG. BT. PROTRUDES 7"
ABOVE GROUND, SURROUNDED BY
A MOUND OF SANDSTONE.

Monument Detail

DOUGLAS COUNTY SURVEYOR
T275
NW
R DLC
6 57
W
1999
OFFICE

New Accessories

- 5/8" IRON ROD WITH PLASTIC CAP MARKED "LS1076" PROTRUDES 6" ABOVE GROUND IN OLD DOWN FENCE LINE, BEARS N5 1/2° W, 17.0 FT
- 1" DIA. B. OAK DOUBLE BLAZED AND SCRIBED "NW DLC 57 CS BT" BEARS S 87 1/2° E, 7.0 FT
- 1 1/2" DIA. W. OAK DOUBLE BLAZED AND SCRIBED "NW DLC 57 CS BT" BEARS S 11° E, 52.1 FT
- 1 1/2" DIA. MADRONE SINGLE BLAZED AND SCRIBED "NW DLC 57 CS BT" BEARS S 54° W, 26.0 FT.

Sketch of Monument, Accessories, and General Area

Location & Comments

CORNER LIES IN OLD
DOWN N-S-FENCE
LINE.
INTERSECTION OF OLD
FENCE LINES RUNNING
SOUTH AND EAST BEARS
N 4° W, 30.5 FT

Comp. Declin. 17 3/4° E
Agency DCSO
Party Chief RANDALL W. SMITH
Notekeeper
Witnesses STEPHEN T. FLUGEL

Address

Surveyor's Seal

REGISTERED
PROFESSIONAL
LAND SURVEYOR

Randall W. Smith
EXPIRES 6-30-2004

OREGON
JULY 25, 1990
RANDALL W. SMITH
2469