P/ # 600 400

615
033115A

GOVERNMENT CORNER RESTORATION FORM

Township 22S Range 13W Sec. 13 County DOUGLAS

State OR Date 3-31-04 No.

Corner Designation

S14	S13
S23	S24

___ Condition Report Only
___ Not Found
✓ Renewed
___ Unrecorded
___ Surveyed In
___ Referenced Out

MONUMENT DETAIL

Previous Renewals 1982 BLM

Monument(s) Found: (Condition and Source)

BLM 1982 BRASS CAP/IRON PIPE SET IN CONCRETE PROTRUDES 2 IN. OUT OF SAND.

FILED
Date: 4/9/2004 By: X
This survey consists of:
Map:
Narrative:
Corner Rpt: 67/6-12

DOUGLAS COUNTY SURVEYOR

Accessories Found:

N/A

C.S. File No 67/6-12A

RENEWAL

Monument Set (Procedure and Description)

NONE

Monument Detail

N/A

New Accessories

2" SHORE PINE DOUBLE BLAZED AND SCRIBED
"X S24 CS BT" BEARS S67°E, 35.5 FT
4" SPRUCE DOUBLE BLAZED AND SCRIBED
"X BT" BEARS N61°E, 18.2 FT
6" SHORE PINE DOUBLE BLAZED AND SCRIBED
"S14 CS BT" BEARS N70°W, 33.0 FT
4" SHORE PINE DOUBLE BLAZED AND SCRIBED
"X CS BT" BEARS S28½°W 54.2 FT

Sketch of Monument, Acessories, and General Area

Location & Comments

1/4 CORNER BETWEEN
S14 AND S13 FOUND
OK 3-31-04
(1600 440)

Comp. Declin. 17½°E
Agency DCSO
Party Chief RANDALL W SMITH
Notekeeper RANDALL W SMITH
Witnesses STEPHEN J FLAVSE

Address

Surveyor's Seal

REGISTERED
PROFESSIONAL
LAND SURVEYOR
Randall W Smith
EXPIRES 6-30-04
OREGON
JULY 26, 1990
RANDALL W. SMITH
2469

67/6-12B