

FILED

GOVERNMENT CORNER RESTORATION FORM

Date: 12-30-2004 By: JC

This survey consists of:

Township 30 S Range 5 W Sec. 17 County DOUGLAS Map: _____

State OR Date 12/15/04 No. 240400 Name: _____
Corner: 67/6-35

Corner Designation

DOUGLAS COUNTY
SURVEYOR

Condition Report Only

Not Found


Renewed

Unrecorded

Surveyed In

Referenced Out

MONUMENT DETAIL



Previous Renewals

Monument(s) Found: (Condition and Source)

3/4" BLM BCLIP APPROX. 1" BELOW
SURFACE, MARKINGS ON
CAP UNREADABLE.

Accessories Found:

- 4' X 6' WOOD PUMPHOUSE NOW MEASURES 5 1/2' X 8'. SE COR. PUMPHOUSE
BEARS N 43° E, 171 1/2 FT. (REC. N 43 1/2° E, 171 1/2 FT.)

- POWER POLE 10" DIA # 4880 RENAMED TO PPL 30-05 205905
BEARS S 49° E, 155 1/2 FT (AGREES W/RECORD)

C.S. File No 67/6-35

