

FILED

GOVERNMENT CORNER RESTORATION FORM

Date: 3/25/2005 By: JC

This survey consists of:

Township 30S Range 6W Sec. 13 County DOUGLAS

State OR Date 2-10-05 No. 037030 Name: Mrs Corner Rpt: 67/10-11

Corner Designation

SSE COR. D.L.C #37

DOUGLAS COUNTY SURVEYOR

Condition Report Only

Not Found

Renewed

Unrecorded

Surveyed In

Referenced Out

MONUMENT DETAIL

Previous Renewals EVANS, MAY 1955.

Monument(s) Found: (Condition and Source)

1 1/4" O.D. IRON PIPE, LEANS NORTHERLY
0.4 FT. PROTRUDING 1.6 FT. OUT
OF GROUND. FENCE CORNER WITH
FENCES RUNNING NORTH AND S35°E
NEAR CORNER (SEE SKETCH)

Accessories Found:

- 22" NOW 32" D. FIR, HEALED BLAZE VISIBLE AND BT TAG DATED 1957
BEARS S32°E, 11.5 FT. B. IRVING MENTIONS THIS TREE ON M20-23
HIS REC. WAS S20°E, 11.0 FT

- 36" NOW 42" B. OAK, PREVIOUSLY OPENED BLAZE WITH ROTTED CENTER
BEARS N31 1/2°W, 11.9 FT. AGREES W/REC O.B.T.

I:
I:\WPWIN\RANDY\TPCW\JOB.TRV

[[Traverse:1 Area:6162.86SqFt 0.14Acres Distance Factor:1.000000000]]

Point	Type	Bearing	Horiz Dist	Radius	Arc Length	Delta	Northing	Easting	Description
45							0.000	0.000	
46		N15°11'00"E	155.400				149.975	40.701	
47		S1°29'30"W	264.000				-113.935	33.828	
48		N25°00'00"W	149.500				21.558	-29.353	
45		S53°42'19"E	36.419				0.000	0.000	

49

COMPUTED RECORD
PER M 20-23

33" B.O.

I:\WPWIN\RANDY\TPCWJOB.TRV

[[Traverse:2 Distance Factor:1.000000000]]

Point	Type	Bearing	Horiz Dist	Radius	Arc Length	Delta	Northing	Easting	Description
-------	------	---------	------------	--------	------------	-------	----------	---------	-------------

46							149.975	40.701	
----	--	--	--	--	--	--	---------	--------	--

S3°27'00"W 168.400

49							-18.119	30.567	
----	--	--	--	--	--	--	---------	--------	--

N59°20'29"W 35.534

45							0.000	0.000	
----	--	--	--	--	--	--	-------	-------	--

COMPLETED RECORD

50									
----	--	--	--	--	--	--	--	--	--

PER M 20-23

16" B.O.