

GOVERNMENT CORNER RESTORATION FORM

FILED

Date: 10/16/07 By: JC

Township 26S Range 3W Sec. 28

County DOUGLAS This survey consists of:

State OR Date 10/3/07

No. 300240 Narrative:

Corner Designation

Corner Rpt: 67/24-28

W 1/4 Cor SEC. 28

DOUGLAS COUNTY SURVEYOR
Condition Report Only
Not Found
Renewed
Unrecorded
Surveyed In
Referenced Out

Previous Renewals 2007

Monument(s) Found: (Condition and Source)

1 1/2" DIA ALUM CAP MARKED "E.E. ENGINEERING" ON 5/8" IRON ROD PROJECTS 6" ABOVE GROUND.

Accessories Found:

10" DIA. MADRONE IS DOUBLE TRUNK, MOST SOUTHERLY TRUNK IS SCRIBED " 1/4 S 28 RT". CENTER OF ROOT CROWN BEARS S 52° E, 24.3 FT. (REC. S 50° E, 25.5 FT.)

14" DIA. MADRONE, SCRIBE VISIBLE " 1/4 S 29 RT" BEARS S 5° W, 20.5 FT. (REC. S 5° W, 21.0 FT.) THIS TREE IS TO BE REMOVED, AS TOP IS DEAD, TO MAKE WAY FOR NEW FENCE

11" MADRONE IS DOUBLE TRUNK, MOST NORTHERLY TRUNK IS SCRIBED " 1/4 S 28 RT" BEARS N 58 3/4° E, 20.0 FT. TO CENTER OF ROOT CROWN (REC. N 53° E, 19.3 FT.)

12" MADRONE (REC. S 21° W, 68.6 FT.) IS SEEN BUT NOT CHECKED THIS RENEWAL AS IT DOES NOT HAVE DIRECT LINE OF SIGHT (AT TOP OF CLIFF) HOWEVER THIS TREE FALLS IN THE N.W. QUADRANT.

C.S. File No 67/24-28

