

N. 0° 05' 00" W., beginning new measurement.

Ascend over broken SW. slope.

11.80 Spur, slopes S. 75° W.; desc. over NW. slope.

25.10 Creek, 10 lks. wide, course W.; asc. over SW. slope.

26.10 Creek, 1 lk. wide, course S. 50° W.; continue to ascend

31.10 Spur, slopes W.; desc. over NW. slope.

31.20 A point of unknown origin, monumented with an iron rod, 1/2 in. diam., firmly set, projecting 6 ins. above ground, with a steel fence post alongside.

→ 40.085 The cor. of secs. 27, 28, 33, and 34, perpetuated and recorded by W. F. Briggs, County Surveyor, in 1893, and further perpetuated and recorded by John H. Markham, Jr., Registered Engineer No. 2880, in 1950, monumented with an iron pipe, 1 1/4 ins. diam., firmly set, projecting 8 ins. above the ground, from which the remains of an original bearing tree:

A root hole, bears S. 30° W., 38 lks. dist., with a down and rotted oak alongside, size indeterminate, with axe marks visible on rotted blaze.

and bearing trees mkd. by Briggs

OBT- An oak, 34 ins. diam., bears S. 51° E., 153 lks. dist., with healed blaze. (NOW DEAD BUT SOUND AND STANDING.)

An oak, 12 ins. diam., bears N. 59° W., 60 1/2 lks. dist., with a partially healed over rotted blaze.

and bearing trees mkd. by Markham

DEPENDENT SURVEY OF A PORTION OF THE SUBDIVISIONAL LINES,
T. 28 S., R. 5 W., Willamette Meridian, Oregon

18709

CHAINS

An oak, 16 ins. diam., bears S. 24 1/2° E., 33 lks. dist., with healed blaze.

An oak, 13 ins. diam., bears S. 10° W., 52 lks. dist., with healed blaze.

At the corner point

Set a stainless steel post, 28 ins. long, 2 1/2 ins. diam., 22 ins. in the ground, directly over the iron pipe, with brass cap mkd.

T 28 S R 5 W
S 28 | S 27
S 33 | S 34
1988

KODY AND I FOUND
✓ FOUND ALL BLM DESCRIBED
BTS. ALIVE EXCEPT OBT
WHICH IS NOW SOUND STANDING
DEAD TREE
MJT

from which a new bearing tree

An oak, 12 ins. diam., bears N. 71 1/2° E., 32 lks. dist., mkd. T28S R5W S27 BT on the bark.

From the cor. of secs. 26, 27, 34 and 35.

N. 89° 54' 00" W., bet. secs. 27 and 34.

Descend over broken NW. slope, through pastureland with scattering timber.

34.80 Dirt road, 15 lks. wide, bears N. 30° E., and S. 30° W.

39.50 Same dirt road, bears NE. and SW.; enter patches of dense undergrowth.

40.130 Point for the 1/4 sec. cor. of secs. 27 and 34, at proportionate distance; there is no remaining evidence of the original corner.

Set a stainless steel post, 28 ins. long, 2 1/2 ins. diam., 22 ins.

FILED
Date: 8/27/2008 By: JC
This survey consists of:
Map: _____
Narrative: _____
Corner Rpt: 67/25-66

DOUGLAS COUNTY
SURVEYOR

C.S. File No 67/25-66

Stephen J. Flouse
Kody Inda
Aug 2008