

GOVERNMENT CORNER RESTORATION FORM

TOWNSHIP 30 S RANGE 05 W SEC. 29 PLSS # 044040

DOUGLAS COUNTY OREGON

DATE OCTOBER 10, 2012

FILED

Date: 11/15/2012 By: [Signature]

This survey consists of:

Map: \_\_\_\_\_

Narrative: \_\_\_\_\_

Corner Rpt: CS 67/36-43

Corner Designation

SSE | SW  
DLC 44 | DLC 46

DOUGLAS COUNTY  
SURVEYOR

Previous Renewals 1993  
Monument(s) Found: \_\_\_\_\_ (Condition and Source)

- Condition Report
- Not Found
- Renewed
- Unrecorded
- Surveyed In
- Referenced Out

MONUMENT DESTROYED; FALLS IN  
ROCK QUARRY EXCAVATION.

N/A

MONUMENT DETAIL

Accessories Found

ALL ACCESSORIES DESTROYED BY QUARRY EXCAVATION.

C.S. File 67/36-43

RENEWAL

Monument Set (Procedure and Description)

MONUMENT DETAIL

N/A

N/A

New Accessories

N/A

Sketch of Monument, Accessories, and General Area

Location & Comments

N/A

MON LOCATION FALLS IN  
PIT TIER ACCESS ROAD OF  
ACTIVE ROCK QUARRY

Comp. Decline. 15" 2" E  
Agency NCSD  
Party Chief STEPHEN JOHN FLAISE  
Note keeper Stephen John Flaise  
Witnesses MIKE S. KOCH

Surveyor's Seal

REGISTERED  
PROFESSIONAL  
LAND SURVEYOR

*Randall W. Smith*  
Renewal 6-30-2013

OREGON  
JULY 25, 1990  
RANDALL W. SMITH  
2488