

FILED

GOVERNMENT CORNER RESTORATION FORM

Date: 2-13-2013 By: JC

Township 30S Range 5W Sec. _____

County DOUGLAS This survey consists of: _____

State OREGON Date JAN. 25, 2013

No. 059020 Narrative: _____
Corner Rpt: CS 67/38-11

Corner Designation

NW
DLC 59

DOUGLAS COUNTY
SURVEYOR

- ____ Condition Report Only
- ____ Not Found
- Renewed
- ____ Unrecorded
- ____ Surveyed In
- ____ Referenced Out

MONUMENT DETAIL

Previous Renewals 1949, 1966, 1974
Monument(s) Found: (Condition and Source)

FROM THE 1966 RENEWAL A 2 1/2 INCH DIAMETER BRASS CAP (MARKED AS AT RIGHT) ON A 1 INCH I.D. IRON PIPE IS FIRMLY AND PLUMBLY SET PROTRUDING 9 INCHES ABOVE GROUND.

COUNTY SURVEYORS OFFICE
N. W. COR.



D.L.C. NO.
59

L.S. 5

* (MARKS ORIENTED SOUTH)

Accessories Found:

REMAINS OF A VERY LARGE MADRONE, NOW AN OUTER SHELL OF A 4 1/2 INCH DIAMETER 2 FOOT TALL STUMP; BEARS S 11 1/2° E 16 1/2 FEET DISTANT (O.B.T.?).

EVIDENCE OF THE TWO 1949 RENEWAL BEARING TREES.
A 14" FIR, NOW A 31 INCH DIAMETER DOUGLAS FIR WITH A FULLY HEALED BLAZE; BEARS N 4° W, 42 3/4 FEET DISTANT (AS PER 1974 RECORD).
A 12" MADRONE, NOW A LOW SAWN 19 INCH DIAMETER 2 FOOT TALL MADRONE STUMP WITH NO SCRIBING REMAINING; BEARS S 84° W, 18 1/2 FEET DISTANT (AS PER 1974 RECORD).

FROM THE 1974 RENEWAL A 1 1/2" I. P. NOW A 1 1/2 INCH I.D. IRON PIPE, FIRMLY AND PLUMBLY SET PROTRUDING 3 INCHES ABOVE GROUND; BEARS SOUTH 11 1/2 FEET DISTANT (1974 RECORD SOUTH 11 1/2 FT.).

C.S. File No 67/38-11

