

GOVERNMENT CORNER RESTORATION FORM

FILED

TOWNSHIP 24S RANGE 05W SEC. 11 PLSS # 540500

Date: 2/27/2015 By: XC
This survey consists of:

DOUGLAS COUNTY OREGON

DATE DEC. 09, 2014

Map: _____

Narrative: _____

Corner Rpt: CS 67/42-4

Corner Designation

DOUGLAS COUNTY
SURVEYOR

Previous Renewals 1960, 2007
Monument(s) Found: _____ (Condition and Source)

- _____ Condition Report
- _____ Not Found
- Renewed
- _____ Unrecorded
- _____ Surveyed In
- _____ Referenced Out

FROM THE 1960 RENEWAL A 2 1/2 INCH DIAMETER BRASS CAP (MARKED AS AT RIGHT) ON A 1 INCH I.D., 32 INCH LONG IRON PIPE IS FOUND COMPLETELY OUT OF THE GROUND AND LEANING AGAINST A FENCE CORNER POST.

MONUMENT DETAIL

COUNTY SURVEYORS OFFICE

T24S R5W

1/4 S11
S14

1960

Accessories Found

ALL FOUR BEARING TREES FROM THE 2007 RENEWAL ARE IN GOOD CONDITION. A POSITION FOR THE BRASS CAP MON. IS DETERMINED BY A DISTANCE-DISTANCE INTERSECTION MEASURED FROM THE NE AND SW BEARING TREES.

ALL BT BEARINGS AND DISTANCES ARE CHECKED FROM ABOVE DETERMINED MONUMENT POSITION AND ARE FOUND TO AGREE WITH 2007 RENEWAL RECORD. CHANGES IN BEARING TREE SIZE ARE NEGLIGIBLE.

C.S. File 67/42-4

RENEWAL

Monument Set (Procedure and Description)

MONUMENT DETAIL

N/A

FOUND BRASS CAP MON. IS SET AT POSITION DETERMINED FROM FOUND BT'S AND NOW SITS PLUMB AND PROTRUDES 2 INCHES ABOVE GROUND, WITH THE CAP STAMPING ORIENTED TO NORTH.

New Accessories

N/A

Sketch of Monument, Accessories, and General Area

Location & Comments

SEE 2007 RENEWAL

THE CENTER OF A FENCE CORNER POST WITH FENCES RUNNING EAST-WEST AND SOUTH; BEARS (APPROX.) SOUTH, 1 FOOT DISTANT. MONUMENT IS ON GENTLE NE SLOPE IN OPEN OAK WOODLAND WITH SCATTERED MADRONE AND FIR. SE QUADRANT IS MAINLY PASTURE.

Comp. Decline. 15' 1/4" E
Agency D.C.S.O
Party Chief STEPHEN JOHN FLAUSE
Note keeper Stephen John Flause
Witnesses MIKE S. KOCH



RENEWAL 12/31/15