

~~DUPLICATE?~~
STILL OK 10/2020

FMS OK
8/27/20

TOWNSHIP 26 RANGE 02 POINT IDENTIFIER # 200200

PRIMARY CORNER DESCRIPTION Cor Secs 29, 30, 31, & 32

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

A roothole, bears S.7°E., 11.9 ft., with a fallen, decayed fir snag, size indeterminate, lying uphill, with no marks visible.

✓ A cedar, 27" dia., bears S.38°W., 13.9 ft., with a healed blaze.

✓ A sawed fir stump, 26" dia., bears N.9°W., 18.5 ft., with a healed blaze.

and a bearing tree mkd. by Quibell

~~GONE~~ A cedar, 12" dia., bears N.75¼°E., 40.5 ft., with ~~RO WORK~~ fragmentary scribe marks visible on partially healed double blazes.

and new accessories

A rebar, 30". long, 5/8" dia., driven 29". in the ground for a reference monument, bears N.72°45'42"E., 81.33 ft., with an aluminum cap mkd. RM T26S R2W 81.3 FT TO COR S29 2011, and an arrow pointing to the cor.

✓ A rebar, 30". long, 5/8" dia., driven 29". in the ground for a reference monument, bears S.34°18'07"E., 75.46 ft., with an aluminum cap mkd. RM T26S R2W 75.5 FT TO COR S32 2011, and an arrow pointing to the cor.

✓ A rebar, 30". long, 5/8" dia., 29". in the ground for a reference monument, bears N.51°21'50"W, 30.12 ft., with an aluminum cap mkd. RM T26S R2W 30.1 FT TO COR S30 2011, and an arrow pointing to the cor.

Corner is located 40 ft. N. of a gravel road, 13 ft. wide, bears N.80°E. and S.80°W, and further located 20 ft. W. of the gravel access road of a rock quarry, 12 ft. wide, bears N.35°E. and S.35°W.

1983 (CORS 96)
Latitude: 43°16'17.874"N Longitude: 122°58'14.858"W

LAT: 43.271636899
LONG: -122.97080855

FILED
Date: 11-2-2020 By: X
This survey consists of:
Map: _____
Narrative: _____
Corner Rpt: CS 67/46-38

DOUGLAS COUNTY
SURVEYOR

C.S. FILE 67/46-38 2