

TOWNSHIP 29 RANGE 02 POINT IDENTIFIER # 440200

**FIR OK**  
**9/24/20**

PRIMARY CORNER DESCRIPTION 1/4-Cor for Secs 27 and 34

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GLO resurvey by Elmer F. Strickler, U.S. Transitman, under Special Instructions dated Jan. 22, 1917 - (DCSO records Vol. 15 Page(s) 6263)

-----

Set an iron post 3 ft. long, 1" dia., 26" in the ground for 1/4 sec. cor., with brass cap mkd:  $\frac{1}{4} \frac{S27}{S34}$   
1917

from which

A Fir 24" dia., bears S.33°30'W., 42 lks. dist. mkd. 1/4 S34 BT.

A Fir 20" dia., bears N.46°30'W., 109 lks. dist. mkd. 1/4 S27 BT.

Douglas Co. Surveyors Office - Clell Goodwin; Vic Cangie - Sept. 22, 1975 - C.S. File 57/36-8

-----

Found - 1917 GLO brass cap on a 1" x 30" Iron pipe, stamped properly.

Orig. 20" now 24" Fir, bears N.46 1/2°W., 71.9 ft.

Orig. SW. BT, a 24" Fir is blown down.

New BT - 7" Fir scribed "1/4 S34 CS BT" in a double blaze bears S.25 1/2°W., 17.6 ft.

Mark Smalley, for Scott Timber Co. Nov. 1997 - M 124-68

-----

Found - 1917 GLO brass cap on iron pipe

New Accessories -

7" Fir, N.12°E., 8.7 ft. scribed "1/4 S BT"

8" Fir, S.58°W., 45.4 ft. scribed "1/4 S BT"

13" Fir, N.89°E., 8.6 ft. scribed "1/4 S BT"

12" Fir, S.71°E., 12.7 ft. scribed "1/4 S BT"

**UNREC. 29" FIR N52°E, 42 MEASD HIGH LOW BLZ NEW SIDE CNTR NAIL**

**LAT: 43.019303360**  
**LONG: -122.932136391**

**FILED**

Date: 12/2/2020 By: X

This survey consists of:

Map: \_\_\_\_\_

Narrative: \_\_\_\_\_

Corner Rpt: CS 67/46-42

**DOUGLAS COUNTY SURVEYOR**