

Filed 11/23/2021

MMGPS

$\pi = 12.105$
 $HI = 0.9935m$

FND OK 7/20/21

TOWNSHIP 23 RANGE 08 POINT IDENTIFIER # 300500

PRIMARY CORNER DESCRIPTION Sec Cor for 8, 9, 16 and 17

Alias _____ Description _____ SEE PG 3

Alias _____ Description _____

Alias _____ Description _____ FOR CHANGES

Alias _____ Description _____

GLO survey by William R. Whipple, Deputy Surveyor, under Contract #622, dated June 23, 1893 (DCSO records Vol. 6 Page(s) 2593)

Set a post 4 ft. long, 4" sq., 2 ft. in the ground for cor. to secs. 8, 9, 16 and 17, mkd. T23S S9 on NE.; R8W S16 on SE.; S17 on SW.; and S8 on NW. faces with 4 notches on S. and E. edges, from which

A Fir 10" dia., bears N.22°E., 11 ks. dist. mkd. T23S R8W S9 BT.

A Fir 10" dia., bears S.40°E., 33 lks. dist. mkd. T23S R8W S16 BT.

A Fir 24" dia., bears S.53½°W., 47 lks. dist. mkd. T23S R8W S17 BT.

A Hemlock 20" dia., bears N.30°W., 14 lks. dist. mkd. T23S R8W S8 BT.

BLM dependent resurvey by Joseph S. Gawron under Group #350 surveyed June 1958 (DCSO records Vol. 33 Page(s) 13834)

The sec. corner, monumented with an iron pipe 2" dia., set 20" in the ground, firmly set, from which the remains of the original bearing trees:

A Fir, dead and fallen, 18" dia., bears S.40°E., 33 lks. dist., with an exposed and burned face.

A Fir, dead and fallen, 30" dia., bears S.53½°W., 47 lks. dist., from which scribe marks are chopped out and exposed.

A stump, burned, bears N.30°W., 14 lks. dist.

At the corner point

Set an iron post, 30" long, 2" dia., 24" in the ground, with brass cap mkd:

T 23 S R 8 W
S 8 | S 9
S 17 | S 16

1958

from which

A Fir snag 50" dia., bears N.12°E., 228 lks. dist. mkd. T23S R8W S9 BT.

A W.Fir 7" dia., bears S.57½°E., 296 lks. dist. mkd. T23S R8W S16 BT.

A W.Fir 12" dia., bears S.26°W., 173 lks. dist. mkd. T23S R8W S17 BT.

A Fir stump 34" dia., bears N.15°W., 42 lks. dist. mkd. T23S R8W S8 BT.

Reset the iron pipe alongside the iron post.

Corner falls on a bench, which has been clear cut and burned.

(Cont. Next Page)

CS 62151-12

TOWNSHIP 23 RANGE 08 POINT IDENTIFIER # 300500

PRIMARY CORNER DESCRIPTION Sec. Cor. for 8, 9, 16 and 17

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

Douglas Co. Surveyors Office - John M. Powell, J. Heritage,
G. Commons, crew - March 16, 1973 - C.S. File 56/25-14

Found - Orig. 30" Fir, now stump, S.53½°W., 31.0 ft.
1958 BT, 34" Fir stump, N.15°W., 27.7 ft. scribed
T23S R8W S8 BT.
1958 BT, 50" Fir snag, N.12°E., 150.5 ft.
1958 GLO brass cap at section corner.
New BTs- 6" W.Fir, S.74°E., 18.4 ft. scribed S16 CS BT.
6" D.Fir N.50°E., 11.3 ft. scribed S9 CS BT.
12" D.Fir N.42°W. 19.7 ft. scribed T23S R8W S8 CS BT
5" D.Fir S.3°W., 15.2 ft. scribed S17 CS BT.

Clyde Mulkins - For: IP Timberlands - March 1995/May 2015 -
M169-50 (filed 7/2/2015)

Found - A 3" 1958 BLM brass cap at the corner, from which:
An 18" DF with a healed face bears N.42°W. 19.7 ft.
A 13" DF with a healed face bears N.50°E. 11.3 ft.
A 14" Hemlock with a healed face bears S.74°E. 18.4 ft.
A 10" DF with a healed face bears S.3°W. 15.2 ft.
50" DF snag with visible scribes bears N.12°E. 150.5 ft.
23" GF with a healed face bears S.57½°E. 195.4 ft.

Ronald L. Rice, Ward NW - Feb. 18, 2009 - C.S. File 65/66-10

Found - ¾" GLO brass cap dated 1958 with the following
accessories:
44" D. Fir snag bears N.12°E. 150.5' visible
scribing
17" Hemlock bears S.74°E. 18.4' healed face (Record
W. Fir)
16" D.Fir bears N.50°E., 11.3' healed face
23" D.Fir bears N.42°W., 19.7' healed face
26" W.Fir bears S.57½°E., 195.4' healed face.
Note - Corner has steel post adjacent to it. All BTs have
red painted bands and yellow tags.
Dec. 16°E

BLM dependent resurvey by Edith M Forkner, Cadastral
Surveyor, under Group #2781, surveyed May/Aug. 2015 - (DCSO
records Vol. 58 Page(s) 23415-6)

The cor of secs 8, 9, 16, & 17, perpetuated by the Douglas Co
Surveyor's Office in 1973; monumented with an iron post, 2"
dia., firmly set, projecting 9" above ground (alongside of
which is an iron pipe, 2" dia., firmly set, projecting 13"
above ground), with a brass cap (properly) mkd. cont.

CS 67/51-12

TOWNSHIP 23 RANGE 08 POINT IDENTIFIER # 300500

PRIMARY CORNER DESCRIPTION Sec Cor for 8, 9, 16 and 17

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

*NOW BROKEN
15' TALL*

from which the remains of the BTs mkd. by Gawron in 1958

A fir snag, 42" dia., bears N.12°E., 150.5 ft., no marks visible.

A white fir high stump, 26" dia., bears S.47½°E., 195.4 ft., with a healed blaze.

A decayed white fir stump, size indeterminate, bears S.26°W., 114.2 ft., no marks visible.

A decayed fir stump, size indeterminate, bears N.15°W., 27.7 ft., no marks visible.

and the remains of the BTs mkd. by the Douglas Co Surveyor's Office and reported by Gawron

A fir, 18" dia., bears N.51°E., 11.3 ft., with a healed blaze.

A hemlock high stump, 17" dia., bears S.75°E., 18.5 ft., with a healed blaze. (Record, white fir.)

A fir, 25" dia., bears N.41°W., 19.5 ft., with a healed blaze.

and new accessories

An iron rod, 30" long, 5/8" dia., set 27" in the ground for a reference monument, bears S.54°13'47"E, 29.93 ft., with aluminum cap mkd. RM T23S R8W S16 29.9 FT TO COR 2015, and an arrow pointing to the cor.

A fir, 19" dia., bears S.73°W., 44.2 ft., mkd. T23S R8W S17 BT.

Corner is located on the NW. cor. of young fir reproduction, edge bears S. & E. A steel fence post is alongside the cor.

NAD 1983 (2011)

Latitude: 43°34'37.64"N. Longitude: 123°39'49.99"W.

CS 67/51-12