

GOVERNMENT CORNER RESTORATION FORM

FILED

TOWNSHIP 245 RANGE 3 W SEC. 29 PLSS # 200240

Date: 11/23/2021 By: X
This survey consists of:

DOUGLAS COUNTY OREGON

DATE 10/26/21

Map: _____

Narrative: _____
Corner Rpt: CS 67/51-22

Corner Designation

1/4 COR S30/S29

DOUGLAS COUNTY
SURVEYOR

Previous Renewals 2 1/2" BRASS CAP
Monument(s) Found: _____ (Condition and Source)

- Condition Report
- Not Found
- Renewed
- Unrecorded
- Surveyed In

MONUMENT DETAIL

2 1/2" BRASS CAP ON 1" ID IRON
PIPE BY BAKER 1994 M121-58 AEB
R. WARD 2001 M139-34
DCSO 2016 Filed 2020 CS
67/46-20

T245 R3W
S30/S29
1/4
PLS 1978
1994

Accessories Found

BT'S by BAKER 1994
A 10" X 12' D. FIR (DEAD SNAG) N174°E 2.8 FT Healed
BLAZE
A Root Hole S4°E 28.9 FT Uprooted 15" D. FIR
Alongside with healed BLAZE
18" D. FIR S67 1/2°W 15.3 FT Healed BLAZE
A 24' D. FIR N26°W 8.6 FT Healed BLAZE
CARBONITE Post 1' North
BT'S By DCSO 2016
27" D. FIR S4°W 37.0 FT Scribes Visible

C.S. File 67/51-22

RENEWAL

Monument Set (Procedure and Description)

MONUMENT DETAIL

New Accessories

Sketch of Monument, Accessories, and General Area

Location & Comments

LAT. $43^{\circ}27'15.86''$ N
 LONG. $123^{\circ}05'22.45''$ W

CORNER IS APPROX.
 26' EAST OF GIBBEL
 ROAD & 10' LOWER

AREA BURNED IN
 ARCHIE CT FIRE
 9-2020

Comp. Decline. 15° E

Agency DCSO

Party Chief S. FLOUSE

Note keeper

Witnesses J LOR SUNG

**REGISTERED
 PROFESSIONAL
 LAND SURVEYOR**

Ronald A. Quimby

**OREGON
 JULY 14, 1978
 RONALD A. QUIMBY
 1854**

CS 67/51-22

Expires: 12/31/2022

BEST LOCK 15V1

FND. OK (SEE BELOW) 10/26/21

TOWNSHIP 24 RANGE 03 POINT IDENTIFIER # 200240

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 29 & 30

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GLO survey by W.H. Byars under contract #152, dated June 3, 1871 - (DCSO records Vol. 7 Page(s) 2958)

Set 1/4 sec. post from which
 A cedar, 24" dia., bears N.40°W., 8 lks.
 A fir, 8" dia., bears S.85°E., 22 lks.

Douglas Co. Surveyors Office - Vernon "Ray" Tracy - April 1968 - C.S. File 54/27-219

Reported as not found
 Logged & burned.

Daniel Baker - Weyerhaeuser Co. - 12/15/94 - M 121-58 A&B

Set- 1 1/4" X 36" Iron pipe with brass cap dated 1994
 13" fir, S.4°E. 28.9', scribed "1/4 S29 BT"
 12" fir, S.76°W. 14.6', scribed "1/4 S30 BT"
 9" fir, N.78°E. 2.8', scribed "1/4 S29 BT"
 16" fir, N.26°W. 8', scribed "1/4 S30 BT"
 6' Fencepost 1' north.

FD. Ok by R. Ward, 12/2001 - M 139-34

Douglas Co. Surveyors Office - Crew: Stephen J Flaue & Mike Koch - 6/14/2016 (Filed 3/17/2020) - C.S. File 67/46-20

Found - A 1" i.d. iron pipe set at proportionate distance by Baker in 1994, with a 2 1/2" brass cap projecting 4" above a 8" diameter concrete collar marked:

T24S R3W
 S30|S29
 1/4
 PLS 1978
 1994

DEAD SNAG

BTs by Baker in 1994 -

A 10"x12' tall D.Fir bears N.74°E., 2.8 ft. with a healed blaze (Rec. N.78°E.)

ALL LIVE TREES
2" LARGER

A root hole bears S.4°E., 28.9 ft. with an uprooted 15" D.Fir alongside with a healed blaze.

A 16" D.Fir bears S.67 1/2°W., 15.3 ft. with a healed blaze.

A 22" D.Fir bears N.26°W., 8.6 ft. with a healed blaze. (Rec. 8.0 ft.)

A Carsonite fence post bears North 1 ft.

New BTs- A 25" D.Fir bears S.4°W., 37.0 ft. scribed "1/4 S30" "CS BT"

continued next page

MMGPS BEGIN 9:35

CS 67/51-22

HI = 0.9245M

TOWNSHIP 24 RANGE 03 POINT IDENTIFIER # 200240

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 29 & 30

Alias _____ Description _____

Alias _____ Description _____

Alias _____ Description _____

Alias _____ Description _____

Note - All bearing trees have BT tags attached. All new bearing trees have double blazed faces with bearings measured to the center of the tree at the root crown and distances measured to the side and center of the root crown.

Monument falls in a recent clear-cut on a steep easterly slope approximately 25 ft. east of the center of a gravel access road and approximately 10 ft. lower than the surface of the road.
Compass decl. 15°E.

CS 67/51-22