

GOVERNMENT CORNER RESTORATION FORM

FILED

TOWNSHIP 26S RANGE 2W SEC. 28 PLSS # 300240

Date: 11/23/2021 By: [Signature]
This survey consists of:

DOUGLAS COUNTY OREGON

DATE 11-3-21

Map: _____

Narrative: _____

Corner Rpt: CS 67/51-25

DOUGLAS COUNTY
SURVEYOR

Corner Designation

1/4 COR 29/28

- ___ Condition Report
- ___ Not Found
- Renewed
- ___ Unrecorded
- ___ Surveyed In

Previous Renewals DCSO 1967 CS 54/40-65
Monument(s) Found: (Condition and Source)

MONUMENT DETAIL

2 1/2" DCSO BRASS CAP ON 1"
ID IRON PIPE Projecting 11"
Nygren 1999 CS 65/40-3
Hostetter 2005 M 149-17
BLM Resurvey 2011 Vol 58 pg 22932

COUNTY SURVEYORS
 OFFICE
 T26S R2W
 1/4 S29/S28
 1967

Accessories Found

ORIG. BEARING TREES
28" DEAD Hemlock S33°E 13.6 FT (REC 13.2) Scribes
Visible on Chopped OPEN FACE
DCSO BEARING TREES
Uprooted 13" Hemlock S68 1/2° W 20.3 FT (Root
Hole)
DEAD BURNED 24" CEDAR S58 3/4° W 45.2 FT (REC
44.9 FT) Healed BLAZE

Collar of Stone Scattered ORIGINAL
STONE NOT FOUND

New Accessories

DEAD 11" X 3 1/2' FOOT Hemlock MARKED "L O A" IN BARK S21°W 13° FT

LAT. 43°16'43.90 N
LONG 123°57'03.08" W
NAD 1983 (CURS 96)

Sketch of Monument, Accessories, and General Area

Location & Comments

CORNER IS 250 FT SOUTH OF GRAVEL ROAD AREA BURNED IN ARKIE FIRE 9/2020

Comp. Decline. 14 1/2° E
Agency DCSO
Party Chief S. Fouse
Note keeper J
Witnesses J. LORSUNG

REGISTERED PROFESSIONAL LAND SURVEYOR

Ronald A. Gumbly
OREGON
JULY 14, 1978
RONALD A. GUMBY
1854

Expires: 12/31/2022

CS 67/51-25

11/3/21

TOWNSHIP 26 RANGE 02 POINT IDENTIFIER # 300240

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 28 & 29

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GLO survey by Wm. N Gibb, Deputy Surveyor, under contract No. 783, dated Dec. 3, 1908 - (DCSO records Vol. 10 Page(s) 4239)

Set a granite stone 8x8x12" 8" in the ground for 1/4 sec. cor. marked 1/4 on W face, from which

A hemlock, 10" dia., bears S.33°E., 20 lks., mkd: 1/4 S28 BT

A cedar, 8" dia., bears N.45°W., 51 lks., mkd: 1/4 S29 BT.

Douglas Co. Surveyors Office - Vernon "Ray" Tracy - Jack Heritage - E. West - Aug. 1967 - C.S. File 54/40-65

Found - 8x10x12" stone, set in mound of stone, no marks found.

Orig. 10" now 26" hemlock, alive, S.33°E., 13.2 ft. prev. opened & shows "1/4 S29 BT" scribe.

Also find pieces of overgrowth with reverse scribe. Orig. 8" now 13" cedar snag, N.40°W., 40.0 ft. (rec. N.45°W., 33.7) previously opened & shows "1/4" Open lower & find "BT"

Set - Brass cap at cor. mkd: County Surveyors T26S R2W Office 1967 1/4 S 29 S 28 (Set under 36" long lying across corner point)

New BTs- 7" hemlock N.48°E., 22.0 ft. mkd: 1/4 S28 CS BT.
9" hemlock S.70 1/2°W., 20.1 ft. mkd: 1/4 S29 CS BT.

Note - This corner lies on flat bench area.

Gerald Nygren - For: Seneca Jones Tbr. Co. - April 23, 1999 (Rec'd & filed April 15, 2010) - C.S. File 65/70-3

Fd. 1967 Co. Surveyor brass cap, from which bears:

(Orig.) 26" dia, Hemlock, S.33°E., 13.2 ft. (vis. scribe)

(1967) 11" dia., Hemlock, S.70°30'W., 20.1 ft. (healed face)

(1967) 9" dia., Hemlock, N.48°E., 22.0 ft. (vis. scribe)

FD. Ok by T. Hostetter, 12/2005 - M149-17

BLM Dependent Resurvey by Kenneth W. Saveland, Cadastral Surveyor, under Group No. 2331, Surveyed April/Oct. 2011 - (DCSO records Vol. 58 Page(s) 22932)

The 1/4 sec. cor. of secs. 28 and 29, perpetuated by the Douglas County Surveyor's Office in 1967, monumented with an iron post, 1 1/4" dia., firmly set, projecting 14" above a collar of stone, (lying out of the ground nearby is the original igneous stone (Record, granite) 8x8x12", with marks 1/4 visible) with brass cap (properly) mkd. cont. next pg

2 1/2" BC
ON 1" IR. I.P.
PROT II"

OVER →

CS 67/51-25

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 28 & 29

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

136
 from which the remains of the original bearing trees
 NOW DEAD 28" A hemlock, 27" dia., bears S. 73° E., 13.2 ft., with scribe marks 1/4 S28 BT visible on a previously chopped open and now partially healed blaze.

BURNED TO GROUND - A cedar snag, 12" dia., bears N. 41 1/2° W., 40.0 TO ROOTS ft., with scribe marks 1/4 and other fragmentary scribe marks visible on a chopped open blaze. (Record, N. 45° W., 33.7 ft.)

and the BTs mkd. by the Douglas County Surveyor's Office
 GONE A hemlock, 9" dia., bears N. 45 3/4° E., 22.1 ft., with a healed double blaze.

DOWN TOTAL UPROOT - A partially uprooted hemlock, 13" dia., bears S. 68 1/2° W., ROOT HALF 20.3 ft., with a healed double blaze.

DEAD BURNED - A cedar, 22" dia., bears S. 58 3/4° W., 44.9 ft., mkd. 1/4 S29 HEALED BLZ. BT. 24 452

Incorporate original stone into collar of stone. COLLAR NOW SCATTERED ORIG. STONE NOT FND.
 Corner is located 250 ft. S. of a gravel road, 15 ft. wide, bears N. 60° W. and S. 65° E., in a curve.

NAD 1983 (CORS 96)

Latitude: 43°16'43.90"N Longitude: 122°57'03.08"W

NEW REF

DEAD 11" x 35 FT HEMLOCK MARKED "L O A" S 21° W, 130 F IN BARK