

FND OK

MM GPS 77=9.58
HI=0.759

1/20/21

TOWNSHIP 23 RANGE 08 POINT IDENTIFIER # 300400

PRIMARY CORNER DESCRIPTION Sec. Cor. for 16, 17, 20 and 21

Alias _____ Description _____
 Alias _____ Description _____
 Alias _____ Description _____
 Alias _____ Description _____

LAT $43^{\circ} 34' 37.66''$ N Long $123^{\circ} 39' 49.96''$ W

GLO survey by William R. Whipple, Deputy Surveyor, under Contract #622, dated June 23, 1893 (DCSO records Vol. 6 Page(s) 2590-91)

Set post 4 ft. long, 4" sq., 2 ft. in ground for cor. to secs. 16, 17, 20 and 21, marked T23S S16 on NE.; R8W S21 on SE.; S20 on SW.; and S17 on NW. faces, with 3 notches on S. and 4 notches on E. edges, from which

- A Fir 6" dia., bears N.40°E., 58 lks. dist., mkd. T23S R8W S16 BT.
- A Fir 24" dia., bears S.82°E., 105 lks. dist. mkd. T23S R8W S21 BT.
- A Fir 40" dia., bears S.24°W., 33 lks. dist. mkd. T23S R8W S20 BT.
- A Fir 30" dia., bears N.18°W., 79 lks. dist. mkd. T23S R8W S17 BT.

Douglas County Surveyors Office - Vernon "Ray" Tracy and crew April 1966 - C.S. File 54/12-37

Found - Orig. 40" now 60" Fir, S.24°W., 21.8 ft find "8" scribe and reverse.
 Orig. 30" now 50" Fir, N.18°W., 52.1 ft scar. We do not open.
 No trace other original BTs.

FILED
 Date: 4-7-22 Open and By: X
 This survey consists of: _____ shows
 Map: _____
 Narrative: _____
 Corner Rpt: CS 67 / 51-29

Set Brass cap at cor. mkd: County Surveyors Office
 T 23 S R 8 W
 S 17 | S 16
 S 20 | S 21
 1966

DOUGLAS COUNTY SURVEYOR

New BTs- 13" Hemlock S.21°E., 19.4 ft. mkd. T23S R8W S21 CS BT.
 24" Hemlock N.61°E., 19.1 ft. mkd. T23S R8W S16 CSBT
 16" Hemlock N.37½°W., 22.2 ft. mkd. T23S R8W S17 CS BT.
 11" Hemlock S.59°W., 14.9 ft. mkd. T23S R8W S16 CSBT
 Corner lies 30 ft. North of road on top of ridge.

Fd. OK, March 1971 by DCSO, J. Powell - C.S. File 54/12-71

Clyde Mulkins - For: IP Timberlands - March 1995/May 2015 - M169-50 (filed 7/2/2015)

Found - A 3" 1966 County brass cap at the corner from which:
 A 60" DF stump with opened face bears S.24°W. 21.8 FT
 A 50" DF stump with scar bears N.18°W. 52.1 ft.
 A 17" Hemlock stump with visible scribes bears S.21°E. 19.4 ft. continued next page

C.S. FILE 67/51-29¹

PRIMARY CORNER DESCRIPTION Sec. Cor. for 16, 17, 20 and 21

Alias	Description
Alias	Description
Alias	Description
Alias	Description

A 28" Hemlock stump with scribes bears N.61°E. 19.1 ft
A 20" Hemlock stump with scribes bears N.37½°W. 22.2 ft.
A 14' Hemlock stump with scribes bears S.59°W. 14.9 ft.
Corner falls 30 ft. North of paved ridge top road.

Ronald L. Rice, Ward NW - Sept. 2010 - C.S. File 65/69-52

Found - 2½" Douglas County brass cap dated 1966 with the following accessories:

60" D.Fir stump bears S.24°W., 21.8' - open rotted face

50" D.Fir stump bears N.18°W., 52.1' - healed face

Rotted Hemlock stump of indeterminate dia. bears N.61°E., 19.1' - no marks.

Rotted Hemlock stump of indeterminate dia. bears S.59°W., 14.9' - no marks.

New - 17" D.Fir bears S.61°E., 10.5' - blazed, scribed "T23S R8W S21 BT"

15" D.Fir bears S.55°W., 15.7' - blazed, scribed "T23S R8W S20 BT"

13" D.Fir bears N.65°W., 16.0' - blazed, scribed "T23S R8W S17 BT"

14" D.Fir bears N.23°E., 22.4' - blazed, scribed "T23S R8W S16 BT"

Note - Corner has steel cost adjacent to it. All BTs have red painted bands and yellow tags.

Compass decl. 16°E.

BLM dependent resurvey by Edith M Forkner, Cadastral Surveyor, under Group #2781, surveyed May/Aug. 2015 - (DCSO records Vol. 58 Page(s) 23413-4)

The cor. of secs. 16, 17, 20, and 21, perpetuated by the Douglas Co Surveyor's Office in 1966; further perpetuated by Rice, in 2010; monumented with an iron post, 2" dia., firmly set, projecting 11" above ground, with a brass cap (properly) mkd. from which the remains of the original bearing trees

A decayed fir stump, 65" dia., bears S.24°W., 17.2 ft., with no marks visible on open blaze. (Record and slope, 21.8 ft.)

A decayed fir stump, 58" dia., bears N.18°W., 52.1 ft., no marks visible.

and the remains of the BTs mkd. by the Douglas Co Surveyor's Office

A decayed hemlock stump, size indeterminate, bears N.61°E., 22.2 ft., no marks visible. Replace tin cap found lying alongside.

A decayed hemlock stump, size indeterminate, bears S.60½°W., 11.4 ft., with remains of a healed blaze.

continued next page

TOWNSHIP 23 RANGE 08 POINT IDENTIFIER # 300400

PRIMARY CORNER DESCRIPTION Sec. Cor. for 16, 17, 20 and 21

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

and the bearing trees mkd. by Rice

A fir, 17" dia., bears N.24°E., 22.4 ft., with illegible scribe marks visible on partially healed blaze and a nail at the base on the right side center.

A fir, 19" dia., bears S.51½°E., 10.5 ft., with a healed blaze and a nail at the base on the left side center.

A fir, 18" dia., bears S.55¼°W., 15.6 ft., with illegible scribe marks visible on partially healed blaze and a nail at the base on the right side center.

A fir, 15" dia., bears N.66°W., 16.0 ft., with a healed blaze and a nail at the base on the left side center.

An aluminum fence post is alongside the cor.