

GOVERNMENT CORNER RESTORATION FORM

FILED

TOWNSHIP 26 S RANGE 2 W SEC. 27 PLSS # 440200

Date: 4/13/2022 By: SC
This survey consists of:

DOUGLAS COUNTY OREGON

DATE 1-31-22

Map: _____

Narrative: _____

Corner Rpt: CS 67/52-12

Corner Designation

DOUGLAS COUNTY
SURVEYOR

1/4 COR 27
34

Monument(s) Found: (Condition and Source)

___ Condition report

___ Not Found

Renewed

___ Unrecorded

___ Surveyed In

2 1/2 GLD BRASS CAP

Replumed 9" proj Rough stone

Previous Renewals MOUND

GLD RESURVEY 1916-1918 Vol 10
pg 4313

DCSO 1967 CS 54/40-8

Geisler 1983 M 94-80

BLM Resurvey 2011 Vol 58

pg 22928

MONUMENT DETAIL

U.S. GENERAL LAND
OFFICE SURVEY

1/4 527
534
1916

Accessories Found

BURD + 14" D. FIR N 13 1/2° E 23.2 FT

C.S. File 67/52-12

New Accessories

5/8" x 30" I. Rod with yellow DCSO plastic cap
S53°E 29.5 FT in North Road Shoulder

5/8" x 30" I. Rod with yellow DCSO plastic cap
N 84 1/2° W 42.2 FT in North Road Shoulder

Lat 43° 16' 17.33" N
Long 122° 55' 16.56" W

Sketch of Monument, Accessories, and General Area

Location & Comments

See Attached Sheet

CORNER IS 25' NORTH
OF GRAVEL ROAD 12"
WIDE BEARS N 70° W
AND S 85° E IN CURVE

AREA BURNT
9-2020

Comp. Decline. 14 1/2° E

Agency DCSO

Party Chief S. F. Clause

Note keeper

Witnesses J. LORSUNG

REGISTERED
PROFESSIONAL
LAND SURVEYOR

Ronald A. Quimby

OREGON
JULY 14, 1978
RONALD A. QUIMBY
1654

CS 67/52-12

Expires: 12/31/2022

T26S, R02W, 440200

1/31/22



NEW REF.
5/8" I.R. / YELLOW
PLSTC. CAP

N 84 1/2° W, 423'

2011
BLM BT
BURNED DEAD
14" D. FIR

N 13 1/2° E
233'

S 53° E, 295'

NEW REF.
5/8" I.R. / YELLOW
PLSTC. CAP

GRAVEL ROAD

DECLINATION 14 1/2° E

CS 67/52-12

3/5
ENDRO
WALSH
UNITED STATES

MM GPS 1/27/22

RENEWED 1/31/22

TOWNSHIP 26 RANGE 02 POINT IDENTIFIER # 440200

PRIMARY CORNER DESCRIPTION 1/4 Corner Secs. 27 & 34

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

BLM Dependent Resurvey by Kenneth W. Saveland, Cadastral Surveyor, under Group No. 2331, Surveyed April/Oct. 2011 - (DCSO records Vol. 58 Page(s) 22928)

★ SEE PG 1 FOR MONUMENT DESCRIPTION

The 1/4 sec. cor. of secs. 27 and 34, perpetuated by the Douglas County Surveyor's Office in 1967, monumented with an iron post, 1" dia., firmly set, projecting 5" above a collar of stone, with brass cap (properly) mkd.

from which the remains of BTs mkd by Mensch

NO EVID. A sawed, decayed, hemlock stump, 16" dia., bears S.10°E., 4.6 ft., with a healed double blaze.

NO EVID. A root hole bears N.17°W., 10.6 ft., with a fallen, decayed, hemlock snag, size indeterminate, lying alongside, with no marks visible.

and the remains of BT mkd by the Douglas Co Surveyor's Office

NO EVID. A sawed, decayed, hemlock stump, size indeterminate, bears N.51 1/2°E., 15.3 ft., with fallen, decayed hemlock trunk segment lying alongside, size indeterminate, with scribe marks 1/4 S27 CS BT visible on a partially healed blaze.

and new bearing trees

BLAZED, DEND 14" AD. fir, 10" dia., bears N.13 1/2°E., 29.2 ft., mkd. 1/4 S27 BT

NO EVIDENCE A cedar, 5" dia., bears S.53°E., 17.1 ft., mkd. 1/4 S37 BT

Corner is located 25 ft. N. of a gravel road, 12 ft. wide, bears N.70°W. and S.85°E., in a curve.

5/8" X 3/8" I.R./YELLOW PLASTIC DCSO CAP PROT 3" ABV GRND S 53° E, 29.5 FT IN NORTH RD SHOULDR

5/8" X 3/8" I.R./YELLOW PLST. DCSO CAP PROT 3" ABV GRND. N 84 1/2° W, 42 1/2 FT IN NORTH RD SHOULDR.

AM GPS 1/27/22

TIME - 9:30

H.L. - 2,000 M

CS 67/52-12 4/5

ARY CORNER DESCRIPTION 1/4 Corner Secs. 27 & 34

Alias	Description
Alias	Description
Alias	Description
Alias	Description

GLO survey by Wm. N. Gibb, Deputy Surveyor, under contract No. 783, dated Dec. 3, 1908 - (DCSO records Vol. 10 Pg 4232)

Set post, 3 ft. long, & 3" sq., 24" in the ground for the 1/4 sec. cor. marked 1/4 S27 on N & 34 on S face, from which:
A cedar, 10" dia., bears N.10°E., 23 lks., mkd: 1/4 S27 BT.
A fir, 12" dia., bears S.43°W., 34 lks., mkd: 1/4 S34 BT.

GLO resurvey by Fred Mensch, U.S. Cadastral Engineer, under Instructions dated May 25, 1916 & April 16, 1918, - (DCSO records Vol. 10 Page(s) 4313)

Set an iron post, 3 ft. long, 1" dia., 26" in the ground, for 1/4 sec. cor., with brass cap marked:

1/4 S 27
S 34
1916

← U.S. GENERAL LAND OFFICE SURVEY

from which
A hemlock, 16" dia., bears S.10°E., 7 lks. Mkd: 1/4 S34 BT
A hemlock, 10" dia., bears N.17°W., 16 lks. Mkd 1/4 S27 BT
The cor. established by Deputy Gibb in 1909 as 1/4 cor. of secs. 27 & 34, which is a fir, post, 4" sq. 12" above ground, marked and witnessed as described by the surveyor general; bears N.24°30'W., 58 lks.

2 1/2" BC
PROT 15"
LEANING 13 FT. NW'LY

WE RE PLUMB NOW PROT 9" IN
ROUGH MND
OF STONE

I destroy the corresponding cor. of the rejected revision survey and marks on bearing trees.

Douglas Co. Surveyors Office - Vernon "Ray" Tracy - Jack Heritage - E. West - March 1967 - C.S. File 54/40-8

Found - 1916 GLO Brass Cap in good condition & properly Mkd. 16" now 18" Hemlock S.10°E., 4.6 ft. Alive, healed blaze, we do not open.
10" now 16" Hemlock, N.17°W., 10.6 ft. Alive, chopped open several years ago, shows "1/4 S27 scribe, face beginning to rot.

New BT - 14" Hemlock N.51°E. 15.4 ft. Mkd. 1/4 S27 CS BT.
Note - The N.W. corner of Shivigny Mt. Lookout Tower bears S.25°E. The NW BT marked in 1916 is also a BT. mkd, in 1909 Gibb & still shows scribe marks. Gibb's other BT is now broken stump.

R. Geisler, fd. 3 BTs now stumps, 6/1983 - M94-80

continued next page

CS 62/52-12 5/5