

GOVERNMENT CORNER RESTORATION FORM

FILED

TOWNSHIP 255 RANGE 2W SEC. 24 PLSS # 640300

Date: 7/20/2022 By: X  
This survey consists of:

DOUGLAS COUNTY OREGON

DATE 3-29-22

Map: \_\_\_\_\_

Narrative: \_\_\_\_\_

Corner Rpt: CS 67/52-29

DOUGLAS COUNTY  
SURVEYOR

Corner Designation

1/4 COR 524  
525

Monument(s) Found: (Condition and Source)

\_\_\_ Condition report

3/4" BLM BRASS CAP ON  
IRON PIPE ORIG COR STONE  
BURIED ON N.W. EDGE

\_\_\_ Not Found

Renewed

\_\_\_ Unrecorded

Previous Renewals

\_\_\_ Surveyed In

Mc Chesney 1958 CS 53/112-34  
BLM Resurvey 1962 Vol 32 pg 13217  
BLM Resurvey 2001-2002  
Vol 54 pg 20906

MONUMENT DETAIL

1/4 524  
525  
T255 R2W  
1962

Accessories Found

ORIGINAL BT'S  
3' TALL mostly burnt away CEDAR STUMP  
N 38 1/2 E 7.0 FT  
Root Hole Hemlock stump 559°W 3.3 FT  
BEARING trees by SKESICK 2001-2002  
22" BURNT-dead FIR 572°W (REC 563°W) 7.0 FT

RENEWAL

Monument Set (Procedure and Description)

MONUMENT DETAIL

\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_

New Accessories

Burnt SAWN 13" Hemlock Stump N02E 20.6 FT  
PK NAIL Top Center  
Burnt-SAWN 17" Hemlock Stump N139E  
30 FT PK NAIL Top Center  
Burnt-SAWN 13" Hemlock Stump S20E  
17<sup>3</sup> FT PK NAIL Top Center

Sketch of Monument, Accessories, and General Area

Location & Comments

LAT 43°22'23.99"N  
LONG 122°53'01.96"W

on moderate No  
Slope 125 FT  
North of Gravel  
Road

See Attached Sketch

AREA Burnt  
9/2020  
Comp. Decline. 14 1/2° E  
Agency DCSO  
Party Chief S. F. Fause  
Note keeper  
Witnesses J. Loring

REGISTERED  
PROFESSIONAL  
LAND SURVEYOR

*Ronald A. Quimby*

OREGON  
JULY 14, 1978  
RONALD A. QUIMBY  
1654

EXPIRES: 12/31/2022

CS 67/52-29  
215

T25S, R2W, 640300

3/29/22

1/4 S24  
S25

NEW REF.  
BURNED SAWN  
HEMLOCK STUMP  
13" X 1 1/2 FT. TALL

NEW REF.  
BURNED SAWN  
HEMLOCK STUMP  
17" X 2 FT. TALL

N02°E, 206'

N39°E, 300'

O.B.T.  
MOSTLY BURNED AWAY  
3 FT. TALL CEDAR STUMP  
N38 1/2°E, 76'

B.C.

2001-2002  
BLM B.T.  
BURNED DEAD  
22" FIR  
S72°W, 70'

S30°E, 172'

NEW REF.  
BURNED SAWN  
HEMLOCK STUMP  
13" X 1 1/2 FT. TALL



(NO SCALE)

DECLINATION 14 1/2°E

CS 67/52-29  
315

MM GPS 3/29/22  
TIME - 12:05  
H.I. - 2,000M

3/29/22

TOWNSHIP 25 RANGE 02 POINT IDENTIFIER # 640300

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 24 & 25

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GLO Survey by Hezekiah H. Johnson, under Contract #721, dated May 1, 1900 (DCSO records Vol. 9 Page(s) 3596)

Set basalt stone 18x14x9", 12" in the ground for 1/4 sec. cor. marked 1/4 on N face, from which  
A cedar, 20" dia., bears N.44°E., 10 lks., mkd: 1/4 S24 BT.  
A hemlock, 18" dia., bears S.50°W., 4 lks., mkd: 1/4 S25 BT.

FD. OBTs, added "W" nail & plates - Glen McChesney, Weyerhaeuser Co. - 7/30/1958 - C.S. File 53/112-34

BLM dependent resurvey by Floyd A. Brooks, Cadastral Surveyor, under Group #350, surveyed April 1962 - (DCSO records Vol. 32 Page(s) 13217)

The 1/4 sec. cor. of secs. 24 & 25, monumented with a basalt stone, 18x12x9", firmly set 12" in the ground, marked on the N. face, from which the original bearing trees:  
A cedar, 22" dia., bears N.36°E., 11 1/2 lks. with no marks remaining on unhealed and weathered blaze. (Record bearing & distance, N.44°E., 10 lks.)  
A hemlock snag, 20" dia., bears S.56°W., 5 lks., with scribe marks 1 2 visible on partly healed blaze. (Record bearing & distance, S.50°W., 4 lks.)

At the corner point  
Set an iron post, 28" long, 4" diam., 26" in the ground with brass cap marked:  
1/4 S 24  
S 25  
T25S R2W  
1962

from which a new bearing tree  
A cedar, 13" diam., bears N.59 1/2° W., 181 lks., marked S24 BT.

No suitable bearing tree available in sec. 25.  
Deposit the original corner stone alongside the iron post.

BLM resurvey by A. Bert Skeesick, Cadastral Surveyor, Group #1979, surveyed 2001/2002- (DCSO rec. Vol. 54 Page(s) 20906)

The 1/4 sec. cor. of secs. 24 and 25, monumented with an iron post, 2 1/2 ins. diam., firmly set, flush with the ground, (with original stone buried alongside) with brass cap mkd.

STONE AS DESCRIBED ON NW EDGE

3 1/4" BC.

1/4 S 24  
S 25  
T25S R2W  
1962

STONE NOT LOOSED FOR

continued next page

CS 67/52-29  
#15

1 Next PG  
OVER →

3/29/22

TOWNSHIP 25 RANGE 02 POINT IDENTIFIER # 640300

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 24 & 25

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

from which the remains of the original bearing trees  
 3 FT TALL MOSTLY BURNED AWAY A sawed cedar stump, 26" diam., bears N.38½°E, 7.6 ft., with no marks visible on partially opened blaze. (Record, N.36°E.)

ROOT HOLE ONLY A decayed hemlock stump, size indeterminate, bears S.59°W, 3.3 ft., with no marks visible. (Rec S.56°W.) and remains of a bearing tree mkd. by Brooks

REMOVED BY LOGGING A sawed cedar stump, 13" diam., bears N.59½°W., 119.5 ft., with scribe marks ¼ S24 BT visible on open blaze. and new bearing trees

BURNED DEAD NO EVID. A fir, 14" dia., bears S.73°W., 7.0 ft., mkd. ¼ S25 BT.

A fir, 9" dia., bears N.6¾°W., 22.1 ft., mkd. ¼ S24 BT.

Each new bearing tree has a 2½"x ¼" magnetic nail (Mag Nail) driven at the base right side-center.

NEW

BURNED SAWN HEMLOCK	13" x 0.5 FT STUMP	3" 2 PK TOP CNTR,	N02°E,	20.6 FT
"	"	"	N39°E,	30.0 FT
"	"	"	S30°E,	17.3 FT

ON MODERATE NORTH SLOPE, 125 FT. NORTH FROM GRAVEL RD.

CS 67/52-29  
515