

GOVERNMENT CORNER RESTORATION FORM

FILED

TOWNSHIP 26S RANGE 1W SEC. 15 PLSS # 440400

Date: 10/18/2022 By: [Signature]  
This survey consists of:

DOUGLAS COUNTY OREGON

DATE 9/19/22

Map: \_\_\_\_\_

Narrative: \_\_\_\_\_  
Corner Rpt: CS67/54-19

Corner Designation

DOUGLAS COUNTY  
SURVEYOR

1/4 COR 15  
22

Monument(s) Found: (Condition and Source)

\_\_\_ Condition report

2 1/2 DCSD BRASS CAP ON  
1" I. PIPE ORIG STONE ON  
WEST EDGE OF B. CAP projecting 12"

\_\_\_ Not Found

Renewed

\_\_\_ Unrecorded

Previous Renewals

\_\_\_ Surveyed In

SHANER 1967 CS 55/66  
DCSD 1975 CS 57/24-6

MONUMENT DETAIL

Douglas Co. Surveyor

T26S  
1/4 515  
S22  
R1W  
1975

Accessories Found

BT BY SHANER  
BURNT - SAWN 24" X 2 FT Hemlock S10°E 3.3 FT  
(Rec S5°E 3.4. FT) Add 3 1/2" NAIL TOP  
CENTER

BT BY DCSD  
15" X 3" Low Cut Chinquapin Stump N71°W  
7.5 FT Healed BLAZE ON Segment of CUT  
OFF TRUNK

C.S. File 67/54-19

Monument Set (Procedure and Description)

MONUMENT DETAIL

Blank lines for Monument Set procedure and description.

New Accessories

1/8" X 30" Iron Rods with yellow plastic caps up 4"
N 55° E 11.6 FT
S 38° E 13.0 FT
S 8° W 13.0 FT
N 38° W 12.7 FT

Sketch of Monument, Accessories, and General Area

Location & Comments

LAT 43° 17' 57.47" N
LONG 122° 48' 19.38" W

AREA BURNED
9/2020

Comp. Decline. 14 1/2° E

Agency DCSO
Party Chief S FIAUSE
Note keeper
Witnesses J LORSUNG



CS 67/54-19
2/3

MM GPS 8/1/22  
TIME - 10:05  
HL - 2.000M

9/19/22

TOWNSHIP 26 RANGE 01 POINT IDENTIFIER # 440400

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs 15 & 22

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

N 17° 2' W 128' EAST FIRM RIDGE 46'

GLO survey by Fred Mensch, Deputy Surveyor - contract #797 dated April 19, 1910 - (DCSO records Vol. 10 Page(s) 4130-1)

Set a conglomerate stone 12x8x6", 8" in the ground for 1/4 sec. cor. mkd. 1/4 on N face, from which  
A madrone, 14" dia., bears N.42°W., 13 lks., mkd: 1/4 S15 BT  
A madrone, 14" dia., bears S.9°W., 22 lks., mkd: 1/4 S22 BT.

Bruce Shaner - For: USFS - Nov. 1967 - C.S. File 55/66

Found - Conglomerate Stone, 12x8x6" mkd. 1/4 on the north face, and from which stone a:  
Orig., 14" dia. Madrone BT. bears N.42°W. 8.6 ft. now missing but at which point there is a hole in the ground with 6" dia. madrone trees growing alongside  
Madrone BT., Orig., 14" dia., bears S.9°W., 14.5 ft. now missing.  
Set - Hemlock, 4" dia., bears S.5°E., 3.4 ft., I scribed "1/4 S S22 BT"  
Hemlock, 8" dia., bears N.5°E. 77.0 ft., I scribed "1/4 S S15 BT"

Douglas Co. Surveyors Office - Gary Langlitz - Clell Goodwin - Vic Cangie - M Lenora Ladig - 7/22/1975 - C.S. File 57/34-6

Found - A stone, 12x8x6" with a "1/4" marked on the north face firmly set. 1967 From which:  
A 4" now 6" Hemlock marked in 1967 by Shaner bears S.5°E., 3.4 ft alive with scribe marks visible. Shaner's N.E. bearing tree was knocked over by logging operations.

At the corner point, we set a 1"x30" Iron Pipe with brass cap attached. Mkd: DOUGLAS CO. SURVEYOR 1975  
510°E, 33 FT. ✓  
T 26 S  
1/4 S 15  
S 22  
R1W

We place the corner stone alongside the brass cap and mark the following bearing tree:  
An 8" Chinquapin bears N.71°W. 7.5 ft scribed: "1/4 S15 CS BT" on a double blaze. Compass Declination setting: 20° East

<u>5/8" x 30" I.R. / YELLOW PLASTIC DCSO CAP PROT 4"</u>	<u>N 55° E, 116'</u>
"	<u>S 38° E, 130'</u>
"	<u>S 08° W, 130'</u>
"	<u>N 38° W, 127'</u>

DECLINATION 14 1/2° E CS 61/54-19  
3/3

BURNED SAWN STUMP  
24" X 2 FT.

BURNED SAWN LOW CUT STUMP  
15" X 3" TALL

SET ON WEST EDGE OF CORNER  
3 1/2" MAG NAIL TOP CENTER  
2 1/2" B.C.  
PROT 12"

HEALED BLZ ON SEGMENT OF CUT OFF TRUNK