

TOWNSHIP T25S RANGE 3W SEC. 14 PLSS # 500400

Date: 11-1-2023 By: X
This survey consists of:

DOUGLAS COUNTY OREGON

DATE 10-31-22

Map: _____
Narrative: _____
Corner Rpt: CS67/54-30

Corner Designation

Sec Cor. 15/14
22/23

DOUGLAS COUNTY
SURVEYOR

Monument(s) Found: (Condition and Source)

2 1/2" GLO BRASS CAP ON
1 1/2" I.D. IRON PIPE UP 12"

- Condition report
- Not Found
- Renewed
- Unrecorded
- Surveyed In

Previous Renewals

GLO Resurvey 1940 Vol 27
pgs 11557-8
DCSO 1966 C 554/27-54

MONUMENT DETAIL

T25S R3W
S15/S14
S22/S23
1943

Accessories Found

ORIG 1883 BTS
Burned Broken off Rotted 19" X 1 1/2" R. FIR
Stump S37 1/2° E (Rec S35° E) 19.8 FT
Burned Broken off 31" X 6 1/2" FT FIR Stump
S62° W (Rec S64° W) 10.5 FT (Rec 9.2 FT)

1966 DCSO BTS

Singed SAWN 30" X 2 1/2" FT Hemlock Stump
N36° E 5.5 FT BLAZE & PARTIAL SCRIBE
Visible inside

Singed & SAWN 27" X 2 1/2" FT Hemlock Stump
S4° E 21.0 FT (Rec 21.7 FT EVIDENCE OK
FACE INSIDE

ALL BTS have 3/4" mag spikes - top center spiked
if 4ft or less, Right side, center spiked otherwise

Monument Set (Procedure and Description)

MONUMENT DETAIL

Blank lines for Monument Set (Procedure and Description)

New Accessories

Blank lines for New Accessories

Sketch of Monument, Accessories, and General Area

Location & Comments

CORNER IS ON moderate
WNW Slope approx. 200 FT.
South of GRAVEL Spur Road
OCRS Coordinates Cottage
Grove Canyonville Zone
N 204430.187
E 245530.935

AREA Burnt
9-2020
Comp. Decline. 14 1/2' E
Agency DCSD
Party Chief S. FIAUSE
Note keeper
Witnesses J. LORSUNG



CS 67154-30
24

ORC GAS - 9:00

RENEW 10/31/22

TOWNSHIP 25 RANGE 03 POINT IDENTIFIER # 500400

PRIMARY CORNER DESCRIPTION Sec Cor for 22, 23, 15 and 14

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

Found - ^{2 1/2" GLO CAP PROPERLY MKD 1 1/2" 1.0 I.P MON. PROT. 12"} GLO brass cap mkd. 1943, & steel fence post alongside. **RESET STEEL FNC, POST WEST 10 FT.**

WENT NO EVID. Orig. 12" now 16" Fir N.35°E., 27.1 ft., previously opened & shows "T25S RS, scribe. (now dead snag) (1883)

BURNED, BROKEN OFF (ROTTED) 19" x 1 1/2' STUMP Orig. 20" now 27" R. Fir S ^{37 1/2°} 35°E., 19.8 ft. now stump

BURNED, BROKEN OFF 31" x 6' STUMP ^{SCAR GONE} shows scar. (1883) Orig. 32" now 48" Fir S ^{62°} 64°W., ¹⁰⁵ 9.2 ft. alive, shows good scar. (1883) **SCAR NOT VIS.**

SINGED SAWN 30" x 2 1/2' STUMP **NO EVID.** Orig. NW BT, now gone and 1943 BT to NW, now turned out stump. (1883)

New BTs → 7" Hemlock N.36°E., 5.5 ft. mkd. T25S R3W S14 CS BT. **BLAZE AND PARTIAL SCRIBES VISIBLE INSIDE**

WENT NO EVID. 16" Hemlock N.70°W., 47.5 ft. mkd. T25S R3W S15 CS BT.

SINGED AND SAWN 27" x 2 1/2' STUMP 8" Hemlock S.4°E., 21.7 ft. mkd. T25S R3W S23 CS BT. **EVIDENCE OF FACE INSIDE**

DECLINATION

MON. ON MODERATE WNW SLOPE ~ 200 FT SOUTH FROM GRAVELLY SPUR RD.

CS 67/54-30

TOWNSHIP 25 RANGE 03 POINT IDENTIFIER # 500400

PRIMARY CORNER DESCRIPTION Sec. Cor. for 14, 15, 22 and 23

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

Original, Laban H. Wheeler, Under Contract #467 dated April 7, 1883 (DCSO Records, Volume 9 Pages 3684-85)

Set Cedar post 4 ft. long 4 sq., 24" in the ground for cor. to secs. 14, 15, 22 and 23, mkd. T25S S14 on NE., R3W S23 on SE., S22 on SW., and S15 on NW faces, with 3 notches on S. and 2 notches on E. edges, from which

- A Fir 16" dia., bears N.35°E., 41 lks. dist., mkd. T25S R3W S14 BT.
- A Fir 20" dia., bears S.40°E., 30 lks. dist., mkd. T25S R3W S23 BT.
- A Fir 25" dia., bears S.71°W., 14 lks. dist., mkd. T25S R3W S22 BT.
- A Fir 18" dia., bears N.46°W., 34 lks. dist., mkd. T25S R3W S15 BT.

GLO Dependent Resurvey by Norman D. Price, Under Special Instructions dated April, 5, 1940. (DCSO records, Volume 27 Pages 11557-58)

Point for original cor. of secs. 14, 15, 22 and 23, determined at record distances from all old bearing trees. At point for corner, set an iron post, 3 ft. long, 2" dia., 28" in the ground, for corner, with brass cap mkd. T25S R3W

S15	S14
S22	S23

1943 from which

- A Fir 12" dia., bears N.35°E., 41 lks. dist., with partial scribe marks visible on face of partially healed old blaze. (Old BT)
- A Fir 20" dia., bears S.35°E., 30 lks. dist., with partial scribe marks visible on face of partially healed old blaze. (Old BT)
- A Fir 32" dia., bears S.64°W., 14 lks. dist., with old blaze healed. (Old BT)
- A dead Fir 12" dia., bears N.48°W., 34 lks. dist., mkd. T25S R3W S15 BT. (Old BT)
- A Fir 20" dia., bears N.20°W., 46 lks. dist., mkd. T25S R3W S15 BT. (New BT)

Doug. County Surveyors Office - Vernon Tracy; Joe Brady; Jack Heritage - July/Aug. 1966 - C.S. File 54/27-54

(Cont. Next Page)