

GOVERNMENT CORNER RESTORATION FORM

FILED

TOWNSHIP 26S RANGE 2W SEC. 15 PLSS # 400 400

Date: 2/14/2023 By: X  
This survey consists of:

DOUGLAS COUNTY OREGON

DATE 1-19-23

Map: \_\_\_\_\_  
Narrative: \_\_\_\_\_  
Corner Rpt: CS 67/55-26

DOUGLAS COUNTY  
SURVEYOR

Corner Designation

COR 515 only  
522

Monument(s) Found: (Condition and Source)

1918 BLM BRASS CAP FLUSH  
10 Rough MOUND OF  
STONE

- Condition report
- Not Found
- Renewed
- Unrecorded
- Surveyed In

Previous Renewals

GLD Survey 1908 Vol 10 pg 4229  
GLD RESURVEY 1916-1918 Vol  
10. pgs 4316; 4325, 4340  
BLM Resurvey 1959 Vol 30 pg 12729  
LAN 9 2013 CS 65/79-17

MONUMENT DETAIL

T26S R2W  
BTB 31  
516/515  
521/522  
1918

Accessories Found

48" S. PINE N 60°E 20.5 FT HEALED BLAZE  
DOWN DEAD 18" MADRONE ROOTHOLE BOARDS  
S 44°E 10.6 FT FAILED ON FACE N.W. 1/4  
19" D. FIR N 79°W 4.0 FT HEALED BLAZE  
14" D. FIR S 20 1/2 W 20.5 FT HEALED BLAZE  
Burnt but still alive

RENEWAL

Monument Set (Procedure and Description)

MONUMENT DETAIL

---



---



---



---



---



---

New Accessories

---



---



---



---



---



---



---



---



---



---

Sketch of Monument, Accessories, and General Area

Location & Comments

Lat 43°17'56.85"N  
 Long 122°55'58.18"W

AREA BURN  
 9/2020

ADD FLAGGING AND NEW  
 BT TAGS

Comp. Decline. 14 1/2° E  
 Agency DCSO  
 Party Chief S. FIAUSE  
 Note keeper  
 Witnesses J LORSUNG



EXPIRES: 12/31/2024

CS 67/55-26

MM GPS 1/19/23

TIME - 9:20

H.L. - 2.000M

FND OK 1/19/23

ADD FLAGGING AND NEW BT TAGS

TOWNSHIP 26 RANGE 02 POINT IDENTIFIER # 400400

PRIMARY CORNER DESCRIPTION Cor. Secs. 15, 16, 21, & 22

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

BLM dependent resurvey by Irving Zirpel, Jr. & Wm. Glenn, Cadastral Surveyors, Group No. 404, surveyed May/Oct. 1959 - (DCSO Vol. 30 Page(s) 12729)

The cor. of secs. 15 & 22 only, which is also cor. No. 8 of Tract 37, monumented with an iron post, 2" dia., protruding 8" above ground, firmly set in a mound of stone, 3 ft. base, to top, set by Mensch in 1918 with brass cap (properly) mkd: from which 1918 BTs

BC NOW FLUSH WITH TOP OF ROUGH MOUND OF STONE

LIVE 48" SINGED  
DEAD SINGED 20" FALLEN MWLY  
NO EVIDENCE

✓ 2046 ✓  
sugar pine, 32" dia., bears N.60°E., 31 lks., with a healed blaze ✓

ROOT HOLE ✓ 1056 ✓  
A madrone, 18" dia. bears S.44°E., 16 lks., with scribe marks 2 22 B visible on a partially healed blaze. FALLEN ON FACE

✓ 396 ✓ 792 ✓  
A fir snag, 12" dia., bears S.76°W., 12 lks., with a healed blaze. FULLY HEALED SINGLE BLZ.

✓ 2046 ✓  
fir, 10" dia., bears N.74°W., 6 lks., with a healed blaze.

add one new bearing tree  
BURNED STILL ALIVE ✓ 2046 ✓  
A fir, 10" dia., bears S.20°W., 31 lks., mkd: T26S R2W S21 BT. FHSB

FD. Mensch BC, by G Lang, 11/2013 - C.S. file 65/79-17

CS 67/55-26  
3/3