

GOVERNMENT CORNER RESTORATION FORM

FILED

TOWNSHIP 26S RANGE 2W SEC. 14

PLSS # 500440

Date: 2/28/2023 By: XC

This survey consists of:

DOUGLAS COUNTY OREGON

DATE 1-23-23

Map: _____

Narrative: _____

Corner Rpt: CS67/55-32

Corner Designation

1/4 S15/S14

DOUGLAS COUNTY
SURVEYOR

Monument(s) Found: (Condition and Source)

3 1/4" BLM BRASS CAP
up 9"

___ Condition report

___ Not Found

Renewed

___ Unrecorded

___ Surveyed In

Previous Renewals

BLM RESURVEY 1959
Vol 30 pg 12725-6 set
this corner

MONUMENT DETAIL

T26S R2W
1/4
S15/S14
1959

Accessories Found

BURNED - DEAD 15" D. FIR N85°E 39.8 FT
(Roe EAST 33.0 FT) FULLY HEALED SINGLE BLAZE
ADD 3 1/2" MAG NAIL RIGHT SIDE CENTER

C.S. File 67/55-32

RENEWAL

Monument Set (Procedure and Description)

MONUMENT DETAIL

New Accessories

5/8" x 30" I. Rod with DCSD yellow Plastic
CAP up 4" N 84°W 60.8 FT

5/8" x 30" I. Rod with DCSD yellow Plastic
CAP up 4" N 6°W 62.1 FT

Sketch of Monument, Accessories, and General Area

Location & Comments

Lat 43°18'23.49" N
Long 122°54'47.00" W

MONUMENT IS
Approx 75 FT South
OF GRAVEL DRIVEWAY
CURVING SWLY

AREA BURNT
9/2020

Comp. Decline. 14' 20" E
Agency DCSD
Party Chief S. HAUSE
Note keeper
Witnesses J. CORSON

REGISTERED
PROFESSIONAL
LAND SURVEYOR

Ronald A. Quimby

OREGON
JULY 14, 1978
RONALD A. QUIMBY
1654

EXPIRES: 12/31/2024

CS 67/55-32

MM GPS 1/23/23
TIME - 10:05
H.I. - 2.000M

RENEWED 1/23/23

TOWNSHIP 26 RANGE 02 POINT IDENTIFIER # 500440

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 14 & 15

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GLO survey by John A. McQuinn, Deputy Surveyor, under contract No. 466, dated April 5, 1883 - (DCSO records Vol. 10 Page(s) 4201)

Set ash post, 3 ft. long, & 3" sq., 24" in the ground for the 1/4 sec. cor. marked 1/4 S on W face, from which:
An ash, 8" dia., bears N.60°E., 43 lks., mkd: 1/4 S BT.
An ash, 10" dia., bears S.70°W., 13 lks., mkd: 1/4 S BT.

BLM dependent resurvey by Irving Zirpel, Jr. & Wm. Glenn, Cadastral Surveyors, Group No. 404, surveyed May/Oct. 1959 - (DCSO Vol. 30 Page(s) 12725-6)

Point for the 1/4 sec. cor. of secs. 14 & 15, at proportionate distance; there is no remaining evidence of the orig. corner. Set an iron post, 28 long, 2 1/2" dia., 22" in the ground and in a mound of stone, 1 1/2 ft. base to top, with brass cap marked:

T26S R2W
1/4
S 15 | S 14
1959
3 1/4" BC PROP. MKKD.
PROT. 9"

from which
A fir, 8" dia., bears East, 50 lks., mkd: 1/4 S14 BT
A fir, 10" dia., bears N.86°W., 80 lks., mkd: 1/4 S15 BT.

BURNED DEAD 15"
GONE NO EVID.

N88°E 330'
5280
ADD 3 1/2 MAG NAIL RSC
FHSB

From this point the NE cor. of an abandoned wood frame building, bears S.33°31'W., 85 lks., dimensions 13x12 ft., long-side bears South.

From the same point the NW cor. of an abandoned wood frame building, bears S.37°17'E., 109 lks., dimensions 14 1/2 x 10 1/2 ft., long-side bears East.

NEW REFS.

5/8" x 30" I.R. / YELLOW PROTRUDING 4" BEARS N84°W, 60 3/4 FT.
" " " " BEARS N06°W, 62 1/4 FT.

MONUMENT IS APPROX. 75 FT. SOUTH FROM GRAVELLED DRIVEWAY CURVING SW'LY.

CS 67/55-32
3/3