

GOVERNMENT CORNER RESTORATION FORM

FILED

TOWNSHIP 255 RANGE 3W SEC. 3 PLSS # 46060

Date: 2/28/2023 By: JC
This survey consists of:

DOUGLAS COUNTY OREGON

DATE 1-26-23

Map: _____
Narrative: _____
Corner Rpt: C567/55-35

Corner Designation

NE 1/4 S3

DOUGLAS COUNTY
SURVEYOR

Monument(s) Found: (Condition and Source)

3/4" BLM BRASS CAP ON
Iron Pipe up 14"

___ Condition report

___ Not Found

Renewed

___ Unrecorded

___ Surveyed In

Previous Renewals

Set by BLM in 1987
Vol 48 pg 18491

MONUMENT DETAIL

NE 1/4
S3
1987

Accessories Found

BURNED DEAD 28" Red CEDAR S13°E
18.9 FT (REC S18°E 2BLKS) TO 3/2" MAG NAIL
RIGHT SIDE CENTER BLAZE NOT VISIBLE

BURNED OFF 1" X 4 1/2 FT D. FIR N11°W 37.6 FT
(REC N5°W) FULLY HEALED SINGLE BLAZE

Metal LATH 52 FT

C.S. File 67/55-35

RENEWAL

Monument Set (Procedure and Description)

MONUMENT DETAIL

New Accessories

BURNED SAWD 13" X 3 FT Red Cedar Stump
 N 71°E 23.0 FT 3 1/2" MAG NAIL TOP CENTER

Sketch of Monument, Accessories, and General Area

Location & Comments

OCRS COORDINATES Cottage
 Grove - Canyonville zone
 N 217898.527
 E 243732.467

AREA BURNED
 9/2020

Comp. Decline. 14 1/2° E
 Agency DCSD
 Party Chief S. F. A. USE
 Note keeper
 Witnesses J. L. Orsung

REGISTERED
 PROFESSIONAL
 LAND SURVEYOR

Ronald A. Quimby
 OREGON
 JULY 14, 1978
 RONALD A. QUIMBY
 1654

EXPIRES: 12/31/2024

CS 67/55-35 2/3

County Surveyor's Record, Douglas County, Oregon

RTKGPS ORCS CANYONVILLE
217898.527N, 243732.467E

18491 RENEWED 1/26/23

Subdivision of Section 3,
T. 25 S., R. 3 W., Willamette Meridian, Oregon

CHAINS

W 1/16
C S 3 C
1987

from which

A cedar, 10 ins. diam., bears N. 58° E., 18 lks. dist.,
mkd. CW 1/16 S3 BT.

A madrone, 10 ins. diam., bears S. 10° E., 15 lks. dist.,
mkd. CW 1/16 S3 BT.

Deposit a white "DEEP-1" magnetic marker at the base of the
stainless steel post.

60.50 Spur, slopes S.; desc. over SW. slope.

61.90 Ravine, drains S. 10° E.; asc. over SE. slope.

63.75 Spur, slopes S.; desc. over broken SW. slope.

81.200 The 1/4 sec. cor. of secs. 3 and 4.

From the center E 1/16 sec. cor. of sec. 3.

N. 10° 08' 00" W., on the N. and S. center line of the NE 1/4
of sec. 3.

Descend over NW. slope, through heavy timber and dense
undergrowth.

7.70 Creek, 6 lks. wide, course S. 40° W.; across gentle W. slope.

12.450 Point for the NE 1/16 sec. cor. of sec. 3, at intersection with
the E. and W. center line of the NE 1/4.

Set a stainless steel post, 28 ins. long 2 1/2 ins. diam., 22 ins.
in the ground, with brass cap mkd.

T26S, R02W,
460660

FOUND A METAL LATH SOUTH ≈ 2 FT.

NE 1/16
S 3
1987

3 1/4" B.C./I.P. PROT. 14"

from which

BURNED DEAD 28"

~~A cedar, 14 ins. diam., bears S. 13° E., 28 lks. dist.,~~ ADD 3 1/2" MAG NAIL R, S, C,
~~mkd. NE 1/16 S3 BT. BLAZE NO LONGER VISIBLE~~

BURNED OFF STUB 11" x 4 1/2 FT.

~~A fir, 10 ins. diam., bears N. 5° W., 57 lks. dist.,~~
~~mkd. NE 1/16 S3 BT.~~

Deposit a white "DEEP-1" magnetic marker at the base of the
stainless steel post.

Continue across W. slope.

NEW REF: BURNED, SAWN, RED CEDAR STUMP 13x3 FT. TALL
3 1/2" MAG NAIL TOP CNTR. N 71° E, 23° FT.

18.30 Creek, 3 lks. wide, course S. 70° W.; asc. over SE slope.

24.230 The E 1/16 sec. cor. of secs. 3 and 34, on the N. bdy. of the Tp.

From the N 1/16 sec. cor. of secs. 2 and 3.

S. 89° 03' 00" W., on the E. and W. center line of the NE 1/4
of sec. 3.

Ascend over SE. slope, through heavy timber and dense undergrowth.

CS 67/55-35