

GOVERNMENT CORNER RESTORATION FORM

FILED

TOWNSHIP 25S RANGE 2W SEC. 7 PLSS # 100 500

Date: 6/5/2023 By: X  
This survey consists of:

DOUGLAS COUNTY OREGON

DATE 5/17/23

Map: \_\_\_\_\_  
Narrative: \_\_\_\_\_  
Corner Rpt: CS 67/56-18

Corner Designation

CC 13  $\frac{7}{18}$

DOUGLAS COUNTY  
SURVEYOR

Monument(s) Found: (Condition and Source)

BLM BRASS CAP

- Condition report
- Not Found
- Renewed
- Unrecorded
- Surveyed In

Previous Renewals

DCSD 1966 CS 54/27-181  
BLM Resurvey 2010-2011  
Vol 57 pg 22788  
Quimby 2014 M 167-34A & B

MONUMENT DETAIL

T25S | T25S  
R3W | 57 CC  
513 | 518  
R2W  
1943

Accessories Found

Burnt - Dead 27" Cedar N84 $\frac{3}{4}$ °E 61.8 FT  
BLAZE NOT VISIBLE

Burnt - Dead 12" Fir S40 $\frac{3}{4}$ °E 37.8 FT  
Fully healed single BLAZE

BT'S Retaged and Klaged

C.S. File 67/56-18

Monument Set (Procedure and Description)

MONUMENT DETAIL

Blank lined area for Monument Set (Procedure and Description)

New Accessories

Blank lined area for New Accessories

Sketch of Monument, Accessories, and General Area

Location & Comments

OCRS Coordinate System  
Cottage Grove - Canyonville  
Zone

AREA BURNT  
9-2020

N 207466.105

E 255342.091

Comp. Decline. 14 1/2° E  
Agency DCSO  
Party Chief S. F. HAUSE  
Note keeper  
Witnesses J. LORSUNG



EXPIRES: 12/31/2024

CS 67/56-18

PRIMARY CORNER DESCRIPTION CC Cor. Secs. 7 & 18 only, (West)

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GLO Dependent Resurvey by Norman D. Price, Under Special Instructions dated April 5, 1940 (DCSO records, Volume 27 Page 11516)

Proportional Measurement. Set an iron post, 3 ft. long, 2" dia., 30" in the ground, for closing corner of secs. 7 and 18, with brass cap mkd.

	T25S	
T25S	S7	CC
R3W	S18	
S13	R2W	

1943 from which

An I.Cedar 20" dia., bears N.11 $\frac{3}{4}$ °E., 79 lks. mkd. T25S R2W S7 CC BT.

An I.Cedar 12" dia., bears S.63°E., 113 lks., mkd. T25S R2W S18 CC BT.

Douglas Co. Surveyors Office - Ray Tracy; Joe Brady, Jack Heritage - July/Aug. 1966 - C.S. File 54/27-181.

Found - 1943 GLO brass cap mkd.  
 20" now 24" I.Cedar N.11 3/4°E., 52.1 ft. now stump, scribe visible on unhealed blaze.  
 12" now 21" I.Cedar S.63°E., 74.6 ft. alive, shows partial scribe marks on nearly healed blaze.

New BT - 18" I.Cedar N.84°E., 61.2 ft. mkd. T25S R2W S7 CSBT.

This cor. lies on very precipitous SW slope approx. 40 ft. N. of top of 80 ft. bluff, course NW and SE.

BLM Dependent Resurvey by A Bert Skeesick, Cadastral Surveyor Under Group No. 2317, Surveyed June 2010/June 2011 - DCSO records Vol. 57 Page(s) 22788

The closing cor. of secs. 7 & 18, on the W. bdy. of the Tp. monumented with an iron post, 2" dia., firmly set, projecting 8 ins. above the ground, with brass cap (properly) mkd. from which bearing trees mkd. by Price

**BURNED AWAY** A sawed, decayed cedar stump, size indeterminate, bears N.11 $\frac{3}{4}$ °E., 52.1 ft., with scribe marks 2W S7 CC BT visible on a weathered blaze.

**BURNED AWAY** A sawed, decayed cedar stump, 18" dia., bears S.63°E., 74.6 ft., with scribe marks 25 S R2W S18 CC BT visible on a partially healed blaze.

and a BT mkd. by the Douglas Co. Surveyor's Office, in 1966  
**BURNED DEAD** - A cedar 27 $\frac{1}{2}$ " dia., bears N.84 $\frac{3}{4}$ °E., 61.8 ft., with a healed blaze. **BLZ NOT VIS.**

continued next page

43.40204  
122.98979

X WALK BP

5/17/23  
FWD OK  
TAGGED  
FLAGGED

TOWNSHIP 25 RANGE 02 POINT IDENTIFIER # 100500

PRIMARY CORNER DESCRIPTION CC Cor. Secs. 7 & 18 only, (West)

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

**BURNED DEAD**

and a new bearing tree  
**FOUND BTs RETAGGED**  
 12" A fir, 1 1/2" dia., bears S.40 3/4°E., 37.8 ft., mkd. T25S R2W  
 S18 CC BT. **FHSB**

Fd as per rec. by R. Quimby, 2/2014 - M167-34 A&B

**OCRS**

**207466.105 N**  
**255342.091 E**

**CS 67/56-18**  
**414**