

TOWNSHIP 25S RANGE 3W SEC. 34 PLSS # 460140

Date: 6/26/2023 By: JC

This survey consists of:

Map: \_\_\_\_\_

DOUGLAS COUNTY OREGON

DATE 6-7-23

Narrative: \_\_\_\_\_

Corner Rpt. CS67/56-31

Corner Designation

CE 1/16 S 34

DOUGLAS COUNTY  
SURVEYOR

Monument(s) Found: (Condition and Source)

3 1/4" BLM BRASS CAP  
Up 2"

- Condition report
- Not Found
- Renewed
- Unrecorded
- Surveyed In

Previous Renewals

BARNES 1963 CS 51/261A  
Weyerhaeuser 1963 CS 53/113-14

MONUMENT DETAIL

BLM resurvey 2008 VOL 57 Pgs  
22442-3

E 1/16  
C ————— C  
534  
2008

Accessories Found

BURNED 8" X 30 FT FIR SNAAG S 88 1/2° W 11.1  
FT. NEXLED HIGH-LOW BLAZE ADD 3 1/2"  
MAG NAIL RIGHT SIDE CENTER

VERY BURNED 34" X 7 FT SAWD CEDAR STUMP  
S 53° W 21.1 FT FD "W" NAIL ON GROUND  
BELOW BURNED OUT FACE

MOSTLY BURNED AWAY HOLLOWED OUT 20" X 1 FT  
CEDAR STUMP N 37° W 26.8 FT



MM GPS 6/7/23

TIME - 10:15

H.I. - 2.000M

RENEWED 6/7/23

22443

Subdivision of Section 34,  
T. 25 S., R. 3 W., Willamette Meridian, Oregon

FEET	
	<p>iron pipe, 33 ins. long, 1 1/4 ins. diam., loosely set, projecting 12 ins. above a collar of stone, from which the remains of reference trees mkd. by Barnes</p> <p><i>NOT SEEN INSIDE BC MON.</i></p>
<p><i>NOW VERY BURNED 34' X 7 FT. TALL</i></p>	<p>sawed cedar stump, 36 ins. diam., bears S. 53° W., 21 ft. dist. with no marks visible.</p>
<p><i>MOSTLY BURNED AWAY HOLLOWED OUT 20" X 1 FT STUMP</i></p>	<p>sawed, decayed cedar stump, 12 ins. diam., bears N. 87° W., 26.8 ft. dist., with no marks visible.</p> <p><i>FOUND "W" NAIL ON GROUND BELOW BURNED OUT FACE.</i></p>
	<p>At the corner point</p> <p>Set a stainless steel post, 28 ins. long, 2 1/2 ins. diam., 24 ins. in the ground, in a collar of stone with brass cap mkd.</p>
	<p style="text-align: center;"> <math display="block">3\frac{1}{4}'' \text{ B.L.}, \quad \begin{array}{c} \text{E } 1/16 \\ \text{---} \\ \text{C} \quad \text{C} \\ \text{S } 34 \\ 2008 \end{array} \quad \text{PROT } 2''</math> </p>
	<p>from which new bearing trees</p>
<p><i>9" BROKEN OFF DOWN FIR</i></p>	<p>fir, 7 ins. diam., bears S. 14 1/4° W., 13.7 ft. dist., mkd. CE 1/16 S34 BT. <i>BLZ NOT SEEN</i></p> <p><i>ROOT HOLE OBLITERATED</i></p>
<p><i>BURNED 8" X 30 FT. SNAG</i></p>	<p>fir, 6 ins. diam., bears S. 88 1/2° W., 11.1 ft. dist., mkd. X at breast height and BT at base. <i>HEALED HIGH-LOW BLZ.</i></p> <p><i>ADD 3/2" MAG NAIL R.S.C.</i></p>
<p><i>MONUMENT ON MODERATE EAST SLOPE ≈ 75 FT NORTH FROM NORTH FACING VERTICAL</i></p>	<p>Place iron pipe inside the stainless steel post and deposit a magnet in a white plastic case at the base of the stainless steel post.</p> <p>Discontinue posting and blazing. <i>ROCK BLUFF.</i></p>
<p><i>DECLINATION 14 1/2° E</i></p>	<p>S. 84° 58' 01" W., beginning a new measurement. <i>BARNES 1963</i></p>
1367.97	The center 1/4 sec. cor. of sec. 34. <i>CS 51/261A</i>
3941.88	The 1/4 sec. cor. of secs. 33 and 34. <i>CS 53/113-1A</i>
	<p>From the center E 1/16 sec. cor. of sec. 34.</p> <p>N. 0° 31' 48" E., on the N. and S. centerline of the NE 1/4 of sec. 34, posting and blazing. <i>WELCO 1963</i></p>
1330.07	Point for the NE 1/16 sec. cor. of sec. 34, at intersection with the E. and W. centerline of the NE 1/4.
	<p>Set a stainless steel post, 28 ins. long, 2 1/2 ins. diam., 24 ins. in the ground, with brass cap mkd.</p>
	<p><i>NEW REF</i></p> <p><i>BURNED DEAN 10" FIR 3 1/2" MAG NAIL R.S.C. N 56° E 42</i></p>

CS 67/56-31

314

Subdivision of Section 34,  
T. 25 S., R. 3 W., Willamette Meridian, Oregon

FEET	
	<p>A cedar, 23 ins. diam., bears S. 7 1/2° E., 31.7 ft. dist., with a healed double blaze.</p> <p>and a bearing tree mkd. by the Douglas County Surveyor's Office, in 1976, reported by Seibold</p> <p>A cedar, 26 ins. diam., bears N. 77° E., 23.8 ft. dist., with a healed double blaze.</p> <p>Corner is located on a SW. slope, E., 25 ft. dist. from a creek, 3 ft. wide, course S. 35° E.</p> <p>N. 0° 54' 08" E., on the N. and S. centerline of sec. 34.</p>
2768.98	<p>Point for the center 1/4 sec. cor. of sec. 34, at intersection with the E. and W. centerline.</p> <p>Set a stainless steel post, 28 ins. long, 2 1/2 ins. diam., 24 ins. in the ground, with brass cap mkd.</p>
	<p style="text-align: center;">T 25 S R 3 W C 1/4 S 34 2008</p>
	<p>from which</p>
	<p>A fir, 9 ins. diam., bears N. 78 1/4° E., 24.1 ft. dist., mkd. C 1/4 S34 BT.</p>
	<p>A cedar, 7 ins. diam., bears N. 18 1/4° W., 14.4 ft. dist., mkd. C 1/4 S34 BT.</p>
	<p>Deposit a magnet in a white plastic case at the base of the stainless steel post.</p>
	<p>Corner is located E., 185 ft. dist. from a dirt road, 11 ft. wide, bears N. 10° W. and S. 25° E., in curve.</p>
4093.43	<p>Point for the center N 1/16 sec. cor. of sec. 34, no permanent monument set.</p>
5417.88	<p>The 1/4 sec. cor. of secs. 27 and 34.</p>
1367.05	<p>From the 1/4 sec. cor. of secs. 34 and 35.</p> <p>S. 85° 04' 51" W., on the E. and W. centerline of sec. 34, posting and blazing.</p> <p>The center E 1/16 sec. cor. of sec. 34, established by William S. Barnes, Registered Professional Engineer No. 2128, in 1963, filed in the Douglas County Surveyors Office, C.S. File No. 51/261A, monumented by William L. Wilt, Land Agent, in 1963, filed in the Douglas County Surveyors Office, C.S. File No. 53/111, and is accepted as the cor., monumented with an</p>



CS 67/5631  
414