

GOVERNMENT CORNER RESTORATION FORM

FILED

TOWNSHIP 25S RANGE 8W SEC. 24 PLSS # 640300

Date: 6/29/2023 By: X  
This survey consists of:

DOUGLAS COUNTY OREGON

DATE 6-22-23

Map: \_\_\_\_\_  
Narrative: \_\_\_\_\_  
Corner Rpt: CS 67/56-41

Corner Designation

1/4 COR 24  
25

DOUGLAS COUNTY  
SURVEYOR

Monument(s) Found: (Condition and Source)

\_\_\_ Condition report

2 1/2" GLD BRASS CAP ON BENT

\_\_\_ Not Found

IRON PIPE REFERENCED OUT

Renewed

STRAIGHTED RESET IN PROPER LOCATION

\_\_\_ Unrecorded

PREVIOUS RENEWALS UP 10" ROUGH STONE AROUND BASE

\_\_\_ Surveyed In

GLD RESURVEY 1940 Vol. 27 pg'

11543-44

MONUMENT DETAIL

WEYCO, CS 53/113-6 1959

JULIANO 1976 CS 58/130

B/M RESURVEY 2008 VOL

57 pg 22421-2

1/4 524  
525  
1943

Accessories Found

36" BURNT-DEAD CEDAR 58°W 14.2 FT (REC  
S5°W 14.5 FT HEALED BLAZE ADD 3 1/2" MAG

NAIL RIGHT SIDE CENTER

45" X 4 FT SAWN-BURNT-ROTTED FIR STUMP

N 84 1/2° W 46.7 FT (REC 46.2 FT) ADD 3 1/2" MAG

NAIL RIGHT SIDE CENTER

22" X 5 FT TALL BURNED CEDAR CEDAR STUB

N 52° E 6.4 FT (REC 7.0 FT) ADD 3 1/2" MAG

NAIL RIGHT SIDE CENTER

9" X 6" TALL BURNT-SAWN FIR STUMP

N 28° W 9.4 FT (REC N 25 3/4° W 9.1 FT) LOW

BLAZE EVIDENCE ADD 3 1/2" MAG NAIL TOP

CENTER

C.S. File 67/56-41

Monument Set (Procedure and Description)

MONUMENT DETAIL

Blank lines for Monument Set description.

New Accessories

Blank lines for New Accessories description.

Sketch of Monument, Accessories, and General Area

Location & Comments

CORNER ON SOUTH EDGE OF LARGE CLEARCUT ON EAST-WEST CUTTING LINE LARGE SECOND GROWTH TO SOUTH.

CORNER IS APPROX 230 FT EAST OF GRAVEL LOGGING ROAD

BCRS COORDINATE SYSTEM COTTAGE GROVE - CANYONVILLE ZONE

Area Burnt

9/2020

Comp. Decline. 14 1/2° E

Agency DCSO

Party Chief S. F. House

Note keeper

Witnesses J. L. Orsund

N 196406.074

E 252394.947

REGISTERED PROFESSIONAL LAND SURVEYOR

Ronald A. Quimby

OREGON JULY 14, 1978 RONALD A. QUIMBY 1654

EXPIRES: 12/31/2024

CS 67/56-41 213

RENEWED 6/22/23

TOWNSHIP 25 RANGE 03 POINT IDENTIFIER # 640300

PRIMARY CORNER DESCRIPTION 1/4 Cor for Secs 24 and 25

Alias \_\_\_\_\_ Description O.C.R.S. CANYONVILLE COTTAGE GROVE COORDS  
 Alias \_\_\_\_\_ Description \_\_\_\_\_  
 Alias \_\_\_\_\_ Description 196406.074 N  
 Alias \_\_\_\_\_ Description 252394.947 E

Original, Laban H. Wheeler, Under Contract #467 dated April 7, 1883 (DCSO Records, Volume 9 Page 3671)

Set Cedar post 3 ft. long 3" sq., 24" in the ground for 1/4 sec. cor. mkd. 1/4 S on N. face, from which  
 A Fir 8" dia., bears N.10°W., 16 lks., mkd. 1/4 S BT.  
 A Fir 12" dia., bears S.16°E., 22 lks., mkd. 1/4 S BT.

GLO Dependent Resurvey by Norman D. Price, Under Special Instructions dated April, 5, 1940. (DCSO records, Volume 27 Pages 11543-44)

Proportional Measurement. Set an iron post, 3 ft. long 1" dia., 28" in the ground, for 1/4 sec. cor. with brass cap mkd

*PLUMB POSITION OF BEAT BRASS CAP MONUMENT REFERENCED OUT MONUMENT REMOVED STRAIGHTENED AND REPLACED AT THE REFERENCED POSITION; MONUMENT NOW PROTRUDES 10" WE ADD ROUGH STONE AROUND BASE*

1/4 S24  
1/4 S25  
1943

2 1/2" BRASS CAP

from which  
 A Fir 56" dia., bears N.84 1/2°W., 70 lks., mkd. 1/4 S24 BT.  
 A Red Cedar 20" dia. bears S.5°W., 22 lks. mkd. 1/4 S25 BT.

FD. Ok by Weyco. 1959 - C.S. File 53/113-6 Found OK, Nick Juliano, Dec. 1976, C.S. 58/130

BLM Dependent resurvey by A. Bert Skeesick & Kenneth W. Saveland, Cadastral Surveyors and Robert H. Browning, Survey Tech, under Group No. 2212 surveyed July/Oct. 2008 - (DCSO records Vol. 57 Page(s) 22421-2)

The 1/4 sec. cor. of secs. 24 and 25, perpetuated by McChesney, in 1959, monumented with an iron post, 1" dia., firmly set, projecting 8" above a collar of stone with brass cap (properly) mkd. MONUMENT PROT. 8" AND BENT AND LEANING 02 EAST FROM PLUMB

*BURNED DEAD 36" SAWN BURNED AND ROTTED BURNED STUB BURNED SAWN 9" x 6" TALL*

SEE ABOVE  
R.S.C.  
ADD 3 1/2" MAG NAIL  
LOW BLZ EVID.

36" A cedar, 28" dia., bears S.5°W., 14.5 ft., with a healed blaze.  
 8° 45' x 4 FT  
 A sawed, 7 decayed fir stump, 55" dia., bears N.84 1/2°W., 46.2 ft., with a healed blaze.  
 and bearing trees mkd. by McChesney → 22" x 5 FT TALL 6.4  
 A sawed cedar stump, 23" dia., bears N.52°E., 7.0 ft., with no marks visible on a partially healed blaze.  
 and a new bearing tree  
 28° 4  
 A fir, 8" dia., bears N.28°W., 9.1 ft., mkd. 1/4 S24 BT. Center SPIKED  
 3 1/2" MAG NAIL

MONUMENT IS ON SOUTH EDGE OF LARGE CLEARCUT ON EAST-WEST CUTTING LINE  
 LARGE SECOND GROWTH TO SOUTH OF LINE,  
 MON. IS ~ 230 FT. EAST FROM GRAVELLEN SPUR LOGGING RD.