

GOVERNMENT CORNER RESTORATION FORM

FILED

TOWNSHIP 25S RANGE 1W SEC. 4 PLSS # 320660

Date: 7/24/2023 By: SC
This survey consists of:

DOUGLAS COUNTY OREGON

DATE 7-10-23

Map: _____

Narrative: _____
Corner Rpt: CS 67/56-45

Corner Designation

NW 1/16 S4

DOUGLAS COUNTY
SURVEYOR

Monument(s) Found: (Condition and Source)

3/4" BLM BRASS CAP
UP 3" IN ROUGH STONE
MOUND

___ Condition report

___ Not Found

Renewed

___ Unrecorded

___ Surveyed In

Previous Renewals

Shrum M 32-62 1966
BLM Resurvey 1978 V42 Pg 16359

MONUMENT DETAIL

NW 1/16 S4
1978

Accessories Found

Shrum Alum Cap Per M 32-62 N 65 1/2° W
13.2 FT Stamped USPC T25S R1W NW 1/16 Sec 4
RE 4287 1964

17" uprooted - Burned 17" D. Fir S 16 3/4° W
44.9 FT (Root Hole) Fallen on Face Not
seen

Burned - Dead 21" Hemlock N 36° W 33.0 FT
Partly Healed BLAZE Fragmentary Scribes
Visible To 1978 B.C. This tree marked
in 1966 bears N 19 3/4° W 22.4 FT from
1966 Alum Cap

C.S. File 67/56-45

New Accessories

Ref. To 1978 BC

Singed 20" Hemlock N 81° E 20.8 FT
3 1/2" MAG Nail RIGHT side Center

Sketch of Monument, Accessories, and General Area

Location & Comments

MON. IS IN OLD Reprod FOREST
ON SMALL BRUCH ON
moderate ENE Slope

BC Approx 130 FT
EAST OF GRAVEL
ROAD

AREA BURNED
9-2020

LAT 219311.634 N

LONG. 301392.256 E

Comp. Decline. 14 1/2° E
Agency DCSO
Party Chief S. F. HAUSE
Note keeper
Witnesses J. LORSUDG

REGISTERED
PROFESSIONAL
LAND SURVEYOR

Ronald A. Quimby

OREGON
JULY 14, 1978
RONALD A. QUIMBY
1654

EXPIRES: 12/31/2024

CS 67/56-45

16359

Vol 32

MM GPS 7/10/23

TIME - 10:35

H.I. - 2.000M

33

T25S, R1W,
PLSS 320660

381

Subdivision of Section 4, T. 25 S., R. 1 W.,
Willamette Meridian, Oregon

RENEWED 7/10/23

CHAINS
20.20

Top of ascent, slopes E.; desc. 10 ft. over NE. slope.

21.17

Point for the NW 1/16 sec. cor. of sec. 4, at inter-
section with the E. and W. center line of the NW $\frac{1}{4}$.

Set an iron post, 28 ins. long, 2 $\frac{1}{2}$ ins. diam., 24 ins.
in the ground, with brass cap mkd.

NW 1/16 S 4
1978

3 1/4" BC PROT. 3"
IN ROUGH
STONE COLLAR

from which

UPROOTED FALLEN BURNED

17" AD fir, 8 ins. diam., bears S. 16 $\frac{1}{2}$ ° W., 68 lks. 44 88
dist., mkd. ~~NW 1/16 S4 BT.~~ ROOTHOLE
FALLEN ON FACE NOT SEEN

No other suitable trees available within limits.

132 FT
From this point, a corner established by Thomas E. Shrum,
Jr., Registered Engineer No. 4287, in 1964, bears ~~18 FT.~~ FOUND LEANING NELY
N. 65 $\frac{1}{2}$ ° W., 0.20 chs. dist., monumented with an iron ~~PLUMB POSITION.~~ WE MEASURE TO
post, $\frac{3}{4}$ in. diam., loosely set, projecting 20 ins. above ~~MON. IS RE-~~
ground, with aluminum cap mkd. USPC T25S R1W NW 1/16 SEC 4 PLUMBED AND
RE 4287 1964, from which a bearing tree mkd. by Shrum: NOW PROT. 6"

BURNED DEAD 21"

A hemlock, 11 ins. diam., bears N. 19 $\frac{1}{2}$ ° W., 34 lks. 22 44
dist., with scribe marks NW 1/16 S4 BT visible
on open blaze. NOT FULLY HEALED BLZ. SHOWS SOME FRAGMENTARY SCR BG
FROM THE 1978 B.C. THIS TREE BEARS N36° W, 330 FT.

NEW REF. MEASURED
FROM 1978 B.C. MONUMENT
A LIVE BUT SINGED 20"
MONUMENT IS IN OLD REPROD. FOREST ON SMALL BENCH ON MODERATE ENE SLOPE ~ 130 FT EAST
FROM GRAVEL RD.

Leave timber, enter logged area, edge bears N. and E.;
desc. 60 ft. over NE. slope.

22.80

Ravine, drains E.; asc. 215 ft. over broken SE. slope.

26.20

Dirt road, 15 lks. wide, bears N. 80° E. and S. 40° W.,
in curve.

42.75

The W 1/16 sec. cor. of secs. 4 and 33, on the N. bdy.
of the Tp.

From the center N 1/16 sec. cor. of sec. 4.

N. 89° 51' W., on the E. and W. center line of the NW $\frac{1}{4}$
of sec. 4.

Descend 50 ft. over SW. slope, across logged area.

3.20

Creek, 3 lks. wide, course S. 10° E.; asc. 385 ft. over
broken NE. slope.

20.235

The NW 1/16 sec. cor. of sec. 4.

Ascend 215 ft. over E. slope.

22.50

Gravelled road. 30 lks. wide.

CS 62/ 56-45
3/3