

GOVERNMENT CORNER RESTORATION FORM

FILED

TOWNSHIP 26S RANGE 2W SEC. 6 PLSS # 140600

Date: 4/9/2024 By: JC

This survey consists of:

Map: _____

DOUGLAS COUNTY OREGON

DATE 3-19-24

Narrative: _____
Corner Rpt: CS 67/57-4*

DOUGLAS COUNTY
SURVEYOR

Corner Designation

1/4 COR 6/27

Monument(s) Found: (Condition and Source)

BLM BRASS CAP

___ Condition report

___ Not Found

Renewed

___ Unrecorded

___ Surveyed In

Previous Renewals

BLM Resurvey 1959 Vol 30 pg 12751

BLM Resurvey 2018-2020

Vol 59 pg 24063-4

MONUMENT DETAIL

T26S R2W

1/4 56/57
1959

Accessories Found

28" decayed Fir Stump N 57° W
22.4 FT

9" x 8' Fir Stump N 36 1/2° E 33.8 FT

27" Hemlock S 35 1/2° E 36.6 FT (Rec 36.8)

C.S. File 67/57-44
43

New Accessories

42" BURNED FIR S 40° W 14.1 FT 3 1/2"
MAG NAIL RIGHT SIDE CENTER

Sketch of Monument, Accessories, and General Area

Location & Comments

DCRS Coordinate Reference
System Cottage Grove -
Canyonville Zone

AREA BURST
9-2020

N 180 544.238
E 257 827.416

Comp. Decline. 14 1/2° E
Agency DCSD
Party Chief S. F. HAUSE
Note keeper
Witnesses J. LORSUNG



EXPIRES: 12/31/2024

CS 67/57-44

TOWNSHIP 26 RANGE 02 POINT IDENTIFIER # 140600

PRIMARY CORNER DESCRIPTION 1/4 Cor Secs 6 & 7

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GLO survey by John A. McQuinn, Deputy Surveyor, under contract No. 466, dated April 5, 1883 - (DCSO records Vol. 10 Page(s) 4222)

Set post, 3 ft. long, & 3" sq., 24" in the ground for the 1/4 sec. cor. marked 1/4 S on N face, from which:

- A fir, 12" dia., bears S.55°E., 8 lks., mkd: 1/4 S BT.
- A fir, 16" dia., bears N.60°W., 24 lks., mkd: 1/4 S BT.

BLM dependent resurvey by Irving Zirpel, Jr. & Wm. Glenn, Cadastral Surveyors, Group No. 404, surveyed May/Oct. 1959 - (DCSO Vol. 30 Page(s) 12751)

Point for the 1/4 sec. cor. of secs. 6 & 7, at proportionate distance; there is no remaining evidence of the orig. corner. Set an iron post, 28 long, 2 1/2" dia., 25" in the ground with brass cap marked:

T26S R2W
1/4 S 6
 S 7
1959

from which

- A fir, 28" dia., bears N.57°W., 34 lks., mkd: 1/4 S6 BT.
- ~~SOME~~ - A fir, 30" dia., bears S.11 1/2°E., 33 lks., mkd: 1/4 S7 BT.

BLM dependent resurvey by Jeffrey O. Covington, Cadastral Surveyor, under Group No. 2923, surveyed July 2018/March 2020- (DCSO records Vol. 59 Pages 24063-4)

The 1/4 sec. cor. of secs. 6 and 7, reported by Zirpel, Jr., and Glenn in 1959, monumented with an iron post, 2 1/2" dia., firmly set, projecting 5" above ground, with a brass cap (properly) mkd.

from which the remains of the bearing trees reported by Zirpel, Jr., and Glenn

- ✓ A decayed fir stump, 29" dia., bears N.57°W., 22.4 ft., with a healed blaze.

and new bearing trees

- ✓ A fir, 9" dia., bears N.36 1/2°E., 33.8 ft. mkd. 1/4 S6 BT.

- ✓ A hemlock, 27" dia., bears S.35 1/4°E., 36.8 ft. mkd. 1/4 S7 BT

Each new BT has a 2 1/2" x 1/4" magnetic nail (Mag Nail) driven at the base right side-center & each monument established or remonumented has a magnet deposited in a white plastic case at the base of the stainless steel post. Alum. Angle iron driven alongside each monument unless a similar marker was already in place.

NOW 9" x 8"
HIGH STUMP

NEW - 42" FIR BURNED, S 40° W, 14'

CS 67/57-44
213