

GOVERNMENT CORNER RESTORATION FORM

FILED

TOWNSHIP 255 RANGE 2W SEC. 29 PLSS # 260260

Date: 4/9/24 By: K

This survey consists of:

Map: _____

Narrative: _____

Corner Rpt: CS 67/57-46

DOUGLAS COUNTY OREGON

DATE 4-1-24

DOUGLAS COUNTY SURVEYOR

Corner Designation

NE 1/16 529

Monument(s) Found: (Condition and Source)

3/4" BLM BRASS CAP
ON 2" I.D. IRON PIPE
UP 2"

Previous Renewals

BLM Established
IN 1993

Condition report

Not Found

Renewed

Unrecorded

Surveyed In

MONUMENT DETAIL

NE 1/16
529
1993

Accessories Found

BURNED DEAD 14" D. FIR N 53° E 19.0 FT
(REC 26 LKS 17.2 FT) FULLY HEALED
DOUBLE BLAZE ADD 3 1/2" MAG NAIL
RIGHT SIDE CENTER

BURNED SAWN 20" X 6" D. FIR STUMP
N 78° W 11.5 FT FULLY HEALED SINGLE
BLAZE ADD 3 1/2" MAG NAIL RIGHT SIDE
CENTER

C.S. File 67/57-46

RENEWAL

Monument Set (Procedure and Description)

MONUMENT DETAIL

New Accessories

Sketch of Monument, Accessories, and General Area

Location & Comments

OCRS Coordinate System
Cottage Grove - Canyonville
Zone

Mod. on steep
Northwest slope
BURNED FOREST
N.E. 1/4 REST CLEAR
CUT
AREA BURNED
9-20??

N 195624.524
E 263887.550

Comp. Decline. 14 1/2° E
Agency DCSD
Party Chief S. FLAISE
Note keeper
Witnesses J. LORSUM

REGISTERED
PROFESSIONAL
LAND SURVEYOR

Ronald A. Quimby

OREGON
JULY 14, 1978
RONALD A. QUIMBY
1654

EXPIRES: 12/31/2024

CS 67/52-46
2/3

Subdivision of Section 29,
T. 25 S., R. 2 W., Willamette Meridian, Oregon

CHAINS	
	Set a stainless steel post, 28 ins. long, 2 1/2 ins. diam., 26 ins. in the ground, with brass cap mkd.
	W 1/16 C ----- C S 29 1993
	from which
	An alder, 9 ins. diam., bears N. 39° W., 72 lks. dist., mkd. CW 1/16 S29 BT on the bark.
	A fir, 6 ins. diam., bears N. 4° W., 122 lks. dist., mkd. CW 1/16 S29 BT.
	Deposit a white "DEEP-1" magnetic marker at the base of the stainless steel post.
	Continue over creek bottom.
78.20	Old creek channel, 15 lks. wide, bears N. 50° E. and S. 50° W.; continue over creek bottom.
80.530	The 1/4 sec. cor. of secs. 29 and 30.

	From the center E 1/16 sec. cor. of sec. 29.
	N. 0° 43' 00" E., on the N. and S. centerline of the NE 1/4 of sec. 29.
	Descend over broken NW. slope through heavy timber and dense undergrowth.
9.90	Graveled road, 25 lks. wide, bears N. 5° E. and S. 30° W.
13.10	Bottom of descent, slopes S. 85° W.; asc. over SW. slope.
13.70	Graveled road, 20 lks. wide, bears N. 15° E. and S. 30° W.
17.15	Spur, slopes N. 55° W.; desc. over broken NE. slope.
20.585	Point for the NE 1/16 sec. cor. of sec. 29, at intersection with the E. and W. centerline of the NE 1/4.
	Set a stainless steel post, 28 ins. long, 2 1/2 ins. diam., 26 ins. in the ground, with brass cap mkd.
	NE 1/16 S 29 1993
	from which
	A fir, 10 ins. diam., bears N. 53° E., 26 lks. dist., mkd. X BT. FULLY HEALED HIGH-LOW BLAZE
	A fir, 14 ins. diam., bears N. 78° W., 17 lks. dist., mkd. NE 1/16 S29 BT. FHSB

TC 5 S, R 02 W, 260 260

DECLINATION 14 1/2 ° E

RENEWED 4/1/24

ADD 3 1/2" MAG NAIL RSC TO FOUND B.T.S

*3 1/4" BC ON 2" I.D. IRON PIPE
PROT 2" ABOVE GRND.*

BURNED DEAD 14" D. FIR

*17 1/2 190 FT. (STEEP SLOPE
ORIG. DIST. IN ERROR)*

*BURNED, SAWN 20" x 6 FT. TALL D. FIR
STUMP*

MONUMENT IS ON STEEP NORTHWEST SLOPE

BURNED FOREST IN NE'LY QUARANT, REST IS CLEARCUT

*CS 62/57-46
313*