

GOVERNMENT CORNER RESTORATION FORM

FILED

TOWNSHIP 26S RANGE 2W SEC. 32 PLSS # 246100

Date: 4/9/2024 By: xc
This survey consists of:

DOUGLAS COUNTY OREGON

DATE 4-1-24

Map: _____

Narrative: _____

Corner Rpt: CS 67/57-47

Corner Designation

$\frac{1}{4}$ COR $\frac{32}{5}$ T26S
T27S

DOUGLAS COUNTY
SURVEYOR

Monument(s) Found: (Condition and Source)

___ Condition report

___ Not Found

Renewed

___ Unrecorded

___ Surveyed In

2 1/2" DCSO BRASS CAP

UP 15"

Previous Renewals

GLD Survey 1913 Vol 10 pg 4259

DCSO 1967 CS 54/40-33

EDWARDS 2010 M 160-76

MONUMENT DETAIL

COUNTY SURVEYORS
OFFICE

$\frac{1}{4}$ $\frac{S 32 T26S}{SS T27S}$ ^{R2W}

1967

Accessories Found

Shattered Broken 6 1/2 FT MADROVE N 35° W
4.6 FT

34" D. FIR S 35° E 20.1 FT (REC 19.8 FT)

1/16 BLAZE ADD 3 1/2" MAG NAIL RIGHT
SIDE CENTER

SAWN 20" X 8 FT D. FIR STUMP N 8° W

12.8 FT Fully Healed Double BLAZE ADD

3 1/2" MAG NAIL RIGHT SIDE CENTER

31" W. FIR S 1° W 9.0 FT Fully Healed Double
BLAZE ADD 3 1/2" MAG NAIL RIGHT SIDE
CENTER

Metal Post 2.0 FT West

C.S. File 67/57-47

RENEWAL

Monument Set (Procedure and Description)

MONUMENT DETAIL

New Accessories

21" x 1 1/2 FT D. KIR STUMP N 54° W 18.4 FT
3 1/2" MAG NAIL TOP CENTER

Sketch of Monument, Accessories, and General Area

Location & Comments

OCRS COORDINATE SYSTEM
COTTAGE GROVE - CANYONVILLE
ZONE

Forested to South
young Repr to
NORTH
AREA BURNED
9/2020

N 154703.925
E 263191.959

Comp. Decline. 14 1/2° E
Agency DCSO
Party Chief S. F. HAUSE
Note keeper
Witnesses J. LORSUNG

REGISTERED
PROFESSIONAL
LAND SURVEYOR

Ronald A. Quimby
OREGON
JULY 14, 1978
RONALD A. QUIMBY
1654

EXPIRES: 12/31/2024

CS 67/57-47

TOWNSHIP 26 RANGE 02 POINT IDENTIFIER # 240100

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Sec. 32; & S 5, T27-2

MWS - 43.25701, 122.96128

| | |
|------------|------------------|
| Alias_____ | Description_____ |
| Alias_____ | Description_____ |
| Alias_____ | Description_____ |
| Alias_____ | Description_____ |

GLO survey by S.C. Flint, Contract #459, dated August 3, 1882 - (DCSO records Vol. 10 Page(s) 4181-82)

Set Cedar post 3 ft. long, 3' sq., 24" in the ground for 1/4 sec. cor. marked 1/4 S. on N. & S. face, from which
A Laurel 20" dia., bears N.35°W., 7 lks. dist. mkd. 1/4 S BT
A Fir 20" dia., bears S.35°E., 30 lks. dist. mkd. 1/4 S BT.

Fd. and tied corner in GLO survey by C.M. Collier, Deputy Surveyor, under Instructions dated May/Sept. 1913 - (DCSO records Vol. 10 Page(s) 4259)

DECLINATION 14°12'E

RENEWED 4/1/24

Douglas County Surveyors Office - Vernon "Ray" Tracy and crew July 1967 - C.S. File 54/40-33

SHATTERED BROKEN STUMP - 6 1/2 FT TALL HAD NONE

Found - Orig. 20" now 22" Laurel, N.35°W, 4.0 ft., alive, scribe visible on unhealed blaze.

ADD 3 1/2" MAG NAIL R.S.C. TO ALL FOUND BTS EXCEPT MAD.

34" D. FIR - Orig. 20" now 32" D. Fir, S.35°E, 19.8 ft., alive bark scribe "1/4 B" in fair condition.

20' EVIDENCE OF BLAZE NO SCRIBING

Set Brass cap at cor. mkd: County Surveyors Office

BARK SCRIB. NOT VISIBLE

1/4 S 32 T26S R2W
S 5 T27S

2 1/2" 13C MON. PROT. 15"

SAWN 20" X 8 FT D. FIR STUMP

New BTs - 12" D. Fir N.8°W, 12.8 ft. mkd. 1/4 S32 CS BT. **FHDB**
31" 20" W. Fir S.1°W, 9.0 ft. mkd. 1/4 S5 CS BT. **FHDB**

Corner lies on top of ridge, sloping South and E-W cutting line, cut off to North.

FOUND METAL LATH WEST 2 FT.

Fd. DCSO cap & 4 BTs - By D. Edwards, 6/2010 - M160-76

NEW REFERENCE

21" X 1 1/2 FT D. FIR STUMP 3 1/2" MAG NAIL TOP CENTER N54°W, 18 1/4

FORESTED TO SOUTH OF MDL. YOUNG REPROD. TO NORTH

CS 67/57-47

3/3