

GOVERNMENT CORNER RESTORATION FORM

FILED

TOWNSHIP 26S RANGE 4W SEC. 10

PLSS # 500540

Date: 1/9/2025 By: SC
This survey consists of:

DOUGLAS COUNTY OREGON

DATE 1-6-25

Map: _____
Narrative: _____
Corner Rpt: CS 67/59-38

Corner Designation

1/4 S10/S11

DOUGLAS COUNTY
SURVEYOR

Monument(s) Found: (Condition and Source)

DCSO BRASS CAP

- Condition report
- Not Found
- Renewed
- Unrecorded
- Surveyed In

Previous Renewals

- Boyer 1944 C9 33/38 M 4-71
- DCSO 1971 CS 56/1-4
- BAUGHMAN 1990 CS 63/110
- DCSO 1990 CS 64/10-10
- Brown 1995 LP 1995-0041 A-B
- DeGroot 2005 M 198-64

MONUMENT DETAIL

County Surveyors
OFFICE
T 26S R 4W
1/4 S10/S11
1971

Accessories Found

- 40" W. OAK N 52°W 904.6 FT Blaze Rotted
OUT
- 22" W. OAK N 8 1/2°E 117.0 FT Hatched Double
BLAZE IN N-S. KENNELNE
- 17" W. OAK N 14 3/4°W 135.5 FT BLAZE
Not Visible
- Multi Trunk W. OAK Scribed 13" Trunk
N 42°E 114.3 FT

Blank lines for Monument Set (Procedure and Description)

New Accessories

Blank lines for New Accessories

Sketch of Monument, Accessories, and General Area

Location & Comments

BARN CORNER JUST Northerly
OF Fence Intersection
Fences N 8° E and S 67° W
Pasture Land Gentle Slope
Rising To west

MON ON WEST
EDGE OF FARM
ROAD RUNNING
Northerly

OCRS Coordinates
Cottage Grove - Canyonville
zone

Comp. Decline. 14 1/4° E
Agency DCSO
Party Chief S. F. HUSE
Note keeper
Witnesses J. L. Surrency

N 178309.958
E 213260.145

REGISTERED
PROFESSIONAL
LAND SURVEYOR

Ronald A. Quimby

OREGON
JULY 14, 1978
RONALD A. QUIMBY
1654

EXPIRES: 12/31/2026

CS 67/59-38
2/4

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 10 and 11

Alias _____	Description _____
Alias _____	Description <u>DCRS CANYONVILLE COTTAGE GROVE COORDS</u>
Alias _____	Description _____
Alias _____	Description <u>178309.958 N</u>
	<u>213260.145 E</u>

Original - Addison R. Flint, Contract #56 dated March, 1855 (DCSO Records, Volume 11 Page 4439)

Set 1/4 sec. cor. post, from which
 A W.Oak 7" dia. bears N.45°W., 613 lks. dist.
 (Brg. checked on microfilm, lists N.45°W. - VL 11/91)
 A Crab Apple, 2" dia. bears S.75°W., 8 lks dist.
 No trees convenient East of line.

A. Boyer - For: R.B. Oliver, October 1944
 C.S. 33/38 and M 4-71

Found W.Oak tree, now 36" dia. bears N.54°W.
 Set 3/4" x 30" Iron pipe at the 1/4 corner.

Doug. Co. Surveyors Office - John M. Powell; W. Penley;
 J. Heritage - January 1971 - C.S. File 56/1-4

Found - 3/4" Iron pipe set by Boyer. All things check with M 4-71 and C.S. 33/38.
 7" now 36" W.Oak N.54°W., 404.0 ft., Tree shows old axe face. I do not open, probably rotted out.
 Set brass cap at cor. mkd: County Surveyors T 26 S R 4 W Office, 1971 1/4 S10|S11
 New BTs - 13" W.Oak N.8 1/2°E., 117.0 ft. scribed "1/4 S11 CS BT".
 8" W.Oak N.11 1/2°W., 135.5 ft. scribed "1/4 S10 CS BT".
 This corner falls at fence corner, fences running S - E - W.

See Condition Report in C.S. File 61/6-29 - April 16, 1980
 Found OK, G. Baughman, February 1990 - C.S. File 63/110

DECLINATION 14 1/4° E *RENEWED 1/6/25*

Doug. Co. Surveyors Office - Randall Smith; Stephen Flause
 August 28, 1990 - C.S. File 64/10-10

Found - A 1971 DCSO brass cap protruding 12" above ground.
 40" 7" now 38" dia. W.Oak with a previously opened blaze no scribing visible, bears N.52°W., 404.6 ft. (Rec. N.54°W., 404.6 ft.) Orig. BT. *BLAZE ROTTED OUT*
 22" 13" now 15" dia. W.Oak with a fully healed double blaze, bears N.8 1/2°E., 117.0 ft. (1971 BT) *IN N-S FENCELINE*

(Cont. Next Page)

CS 67/59-38
3/4

TOWNSHIP 26 RANGE 04 POINT IDENTIFIER # 500540

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 10 and 11

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

17" 8" now 11" dia. W.Oak with a ~~fully healed single~~ ^{BLAZE NO LONGER VISIBLE} blaze, bears N.14 $\frac{3}{4}$ °W, 135.5 ft. (Rec. N.11 $\frac{1}{2}$ °W. 135.5 ft.)
New BT - A multi-trunk W.Oak double ^{FHDB}blazed and scribed "1/4 S1/
SCRIBED TRUNK 13" CS BT" on ~~11"~~ ^{11"} dia. west trunk, bears N.42°E, 114.3 ft. to center of west trunk at base.
(See condition report in C.S. File 61/6, for additional information). *PASTURE LAND, GENTLE SLOPE RISING TO WEST MONUMENT IS ON WEST EDGE OF FARM RD. RUNNING NORTHERLY*
Found OK by R. Brown - April 1995 - L.P. 1995-0041 A & B
Fd ok by K. DeGroot, 10/2005 - M148-64

TO BARN. CORNER IS JUST NORTHERLY OF INTERSECTION OF FENCES RUNNING NORTH; NORTH 8° EAST AND SOUTH 67° WEST.

C S 67/59-38
4/4