

GOVERNMENT CORNER RESTORATION FORM

FILED

TOWNSHIP 305 RANGE 8W SEC. 9

PLSS # 400546

Date: 1-29-2025 By: ke

This survey consists of:

Map: \_\_\_\_\_

Narrative: \_\_\_\_\_

Corner Rpt: CS 67159-53

DOUGLAS COUNTY OREGON

DATE 1-27-25

DOUGLAS COUNTY  
SURVEYOR

Corner Designation

1/4 COR 59/510

Monument(s) Found: (Condition and Source)

2 1/2" DCSO BRASS

Cap Proj 4"

Condition report

Not Found

Renewed

Unrecorded

Surveyed In

Previous Renewals

DCSO 1965 CS 53/67-47

Quimby 2013 CS 65/78-39

MONUMENT DETAIL

County Surveyors  
Office

T30S R8W

1/4 59/510

1965

Accessories Found

32" D. FIR S62°E 8.0 FT

16" D. FIR S38°W 32.0 FT

30" D FIR S26°E 36.8 FT

Monument Set (Procedure and Description)

MONUMENT DETAIL

\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_

New Accessories

24" W. FIRE N 4°W 30.4 MARKED  
1/4 59 TBT ON UNWHEELED SINGLE BLADE  
By Roseburg Resources 4-24

Sketch of Monument, Accessories, and General Area

Location & Comments

OGRS Coordinate System  
Cottage Grove - Canyonville  
Zone

N 52073.582  
E 81281.761

Comp. Decline. 14 1/8° E  
Agency DCSD  
Party Chief S. Finuse  
Note keeper  
Witnesses J. Loring

REGISTERED  
PROFESSIONAL  
LAND SURVEYOR

*Ronald A. Quimby*

OREGON  
JULY 14, 1978  
RONALD A. QUIMBY  
1654

TOWNSHIP 30 RANGE 08 POINT IDENTIFIER # 400540

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 9 & 10 FND. OK 1/27/25

Alias _____	Description _____
Alias _____	Description <u>OCS CANYONVILLE COTTAGE GROVE COORD.S</u>
Alias _____	Description _____
Alias _____	Description <u>52073.582 N</u>
	<u>81281.761 E</u>

GLO survey by W.H. Byars under contract #456, dated July 28, 1882 - (DCSO records Vol. 17 Page(s) 7341)

Set a cedar post 3 ft. long, 3" sq., 18" in the ground, for 1/4 sec. cor., marked 1/4 S on West face; from which

A fir, 14" dia., bears S.62°E., 13 lks., mkd: 1/4 S BT.

A chinquin, 5" dia., bears West, 34 lks., mkd: 1/4 S BT

DECLINATION 14 1/2°E

Douglas Co. Surveyors Office - Vernon "Ray" Tracy - Mike Darby & Jack Barnett - April 1965 - C.S. File 53/67-47

Found ~~32 1/4"~~ now 28" D. fir S.62°E., 8.6 ft. "1/4 S BT" bark scribe.

GONE 5" now 6" chinquin West 22.4 ft. mostly rotted away, found partial face with possible reverse scribe "1"

Set brass cap at cor. mkd: COUNTY SURVEYORS OFFICE 1965

T30S R8W 1/4 S9|S10

New BTs - 16" D. Fir S.38°W, 32.0 ft. mkd: 1/4 S9 CS BT.

30" - 16" D. Fir S.26°E, 36.8 ft. mkd: 1/4 S10 CS BT.

2 1/2" DIAM B.C.  
PROT. 4 INCHES

Fd. OK by R. Quimby, 5/8/2013 - C.S. File 65/78-39

24" W. FIR ROSEBURG RESOURCES 4/24 WK "1459 BT" UNHEALED SINGLE BLAZE N04°W, 30 1/4

MINI GIS  
42.97580  
123.64260  
INTRC. TO 400500 THEN NORTH 1/2 MI. TO  
NEW ROADS LEFT, THEN TAKE 2ND LEFT AT POND