

TOWNSHIP 3/S RANGE 9W SEC. 30 PLSS # 100240

Date: 5/5/25 By: ke
This survey consists of:

DOUGLAS COUNTY OREGON

DATE 4-16-25

Map: _____

Narrative: _____

Corner Rpt: CS 67160-24

Corner Designation

R10W R9W

DOUGLAS COUNTY
SURVEYOR

1/4 cor 25/30

Monument(s) Found: (Condition and Source)

___ Condition report

2 1/2" BRASS CAP ON
IRON PIPE DCSO

___ Not Found

___ Renewed

___ Unrecorded

___ Surveyed In

Previous Renewals

DCSO 1947 CS 54/32-74
Coos County Surveyors
OFFICE - 2015 CS 65/87-62
Hostetter 2015 M 149-54

MONUMENT DETAIL

COUNTY SURVEYORS
OFFICE
R 315 R
10 W 25/30 W
1967

Accessories Found

16" X 3' SAWN W. CEDAR STUMP N51°E
(Rec N52°30'E) 14.58 FT
15" D FIR Broken Top N84°E 10.5' (Rec
N85°E 10.69')
12" D FIR S33 1/2 W 33.5 (Rec S35°W 33.37)
To Nail RIGHT Side Center
9" D. FIR N42 1/2 W 27.96' (Rec N41°W) Nail
RIGHT side Center Fully heated Single
BLAZE
5" D. FIR S45°E (Rec S44°E) 25.65 TO NAIL
RIGHT Side Center
Coos County used a 17° Declination
should have been 15°

Monument Set (Procedure and Description)

MONUMENT DETAIL

Horizontal lines for Monument Set description.

New Accessories

Horizontal lines for New Accessories description.

Sketch of Monument, Accessories, and General Area

Location & Comments

Lat - Long

MON IS ON FPA/
Ground on Edge
of older Reprod
uneven Clearcut
Edge to North e
EAST

LAT 42° 50' 45.623 N

Comp. Decline. 14 1/2° E

Agency DCSD

Party Chief S. FRAUSE

Note keeper

Witnesses J LORSUNG

Long 123° 49' 09.591 W

REGISTERED
PROFESSIONAL
LAND SURVEYOR

Ronald A. Quimby

OREGON
JULY 14, 1978
RONALD A. QUIMBY
1654

EXPIRES: 12/31/2026

CS 67160-24 pg 2/4

TOWNSHIP 31 RANGE 09 POINT IDENTIFIER # 100240

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Sec. 30; & 25, T31-10

Alias _____ Description GEO XT POS. 42° 50' 45.629" N
 Alias _____ Description 123° 49' 09.520" W
 Alias _____ Description _____
 Alias _____ Description LEICA GPS POS. 42° 50' 45.623" N

GLO survey by Wm. H. Byars, Deputy Surveyor, under Contract #727, dated Dec. 20, 1900 - (DCSO records Vol. 19 Page 8175)

Set a Cedar post 4 ft. long, 4" sq., 24" in the ground for ¼ sec. cor. mkd. ¼ S S25 on W.; S30 on E. faces, from which
 A Fir 36" dia., bears N.75°E., 250 lks. mkd. S30 ¼ S BT.
 A Cedar 36" dia., bears N.48°W., 224 lks. mkd. S25 ¼ S BT.

Douglas Co. Surveyors Office - John M. Powell, and crew - April/May 1967 - C.S. File 54/32-74

Found - Old scribed stake "¼S" visible & ¾" I.Pipe, badly rusted.

36" Cedar now snag, N.48°W., 147.8 ft scribe visible NE. BT falls in logged area and skid trails.

Set Brass cap at cor. mkd: County Surveyors Office

R	T 31 S	R
10 ¼ S 25	S 30	9
W	1967	W

New BTs- 12" D.Fir S.29°W., 18.6 ft. mkd. ¼ S25 CS BT.

10" Cedar N.51°E., 14.5 ft. mkd. ¼ S30 CS BT.

Coos County Surveyors Office - Michael Dado, Surveyor - Crew: Matthew Martin & Bill Hales - 3/19/2015 - C.S. File 65/87-62

Found - 2½" brass cap on a 1¼" O.D. iron pipe, 1.0' tall, in good condition and solid in the ground, **leaning slightly** to the South. We find a 1" iron pipe, 2.05' tall, of unknown origin, fd by Powell in 1967, S.78°E., 0.35'. **We set** a D.Fir post 2' North and **paint** the top in blue. There is a broken off wood post 1' North of the BCIP.

1900: 35" W.Cedar snag, 30' tall, N.45°15'W., 149.44' to left side center. We find visible scribes and a 1958 BLM tag in place. **We paint** the face and a band around the snag in blue. Snag falls near an old logging road. GOOD CONDITION

1900: 17" W.Cedar N. ~~52°30'~~ E., 14.58' to right side center. We find a healed blaze but no tag. **We paint** the blaze and a band around the tree in blue and attach a new yellow tag. GOOD CONDITION

Laush Tag 1950 (unrecorded): 15" D.Fir with top broken and touching the ground, yet still attached to the main stem, N. ~~85°~~ E., ~~10.89'~~ to left side center. There is a healed scar on the right side. We paint the scar and a band around the tree in blue. FAIR Condition. Cont. next pg

TOWNSHIP 31 RANGE 09 POINT IDENTIFIER # 100240

CS 67/60-24 pg 3/4

42.84598
123.81924

RENEWED 4/16/25

SAWN STUMP 16" X 3 FT. TALL

N51°E

N84°E, 105'

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

New - 12" 9" ✓ D. Fir ✓ S. ~~35°~~ ^{33 1/2°} W., ~~33.37'~~ ^{33.5'} to a nail at right side ✓ center. We blaze and scribe "1/4 S25 BT". We paint the blaze, scribes and a band around the tree in blue and attach a yellow Coos County tag. **FHSB**

9" 7" ✓ D. Fir ✓ N. ~~41°~~ W., 27.96 ✓ to a nail at left side ✓ center. We blaze and scribe "1/4 S25 BT". We paint the blaze, scribed, and a band around the tree in blue and attach a yellow Coos County tag. **N42 1/2° W FHSB**

5" 4" ✓ D. Fir ✓ S. ~~44°~~ ^{45°} E 25.65 ✓ to a nail at left side ✓ center. We chop a notch low and scribe an "X" high. We paint the notch, "X" & a band around the tree in blue and attach a yellow Coos County tag. **NOW HEALED**

Decl. 17°E. - **2015 RECLINATION SHOULD HAVE BEEN 15°E**
DECLINATION 14 1/2°E (PER NOAA MAGNETIC FIELD CALCULATOR)
 Fd. BC & BTs as per rec. 4/2015 by T. Hostetter M169-54

MONUMENT IS ON MOSTLY FLAT GROUND ON EDGE OF OLDER REPROD. UNEVEN CLEAR CUT EDGE TO NORTH AND EAST.