

GOVERNMENT CORNER RESTORATION FORM

FILED

TOWNSHIP 32S RANGE 9W SEC. 15 PLSS # 440406

Date: 6-19-25 By: IC
This survey consists of:

DOUGLAS COUNTY OREGON

DATE 6-9-25

Map: _____

Narrative: _____

Corner Rpt: CS 67/100-43

Corner Designation

$\frac{1}{4} \frac{15}{22}$

DOUGLAS COUNTY
SURVEYOR

Monument(s) Found: (Condition and Source)

2 1/2" GLD BRASS CAP BROKEN
OFF IRON PIPE 1" O.D
PIPE NEAR PLAIN IN GROUND

___ Condition report

___ Not Found

Renewed

___ Unrecorded

___ Surveyed In

Previous Renewals

ORIG GLD 1916 Vol 21 pg 8898

MONUMENT DETAIL

$\frac{1}{4} \frac{515}{522}$
1917

Accessories Found

35" D. FIR N146°E 58.5 FT (REC N39°E
89 LBS) FULLY HEATED SINGLE BLAZE ADD
3 1/2" MAG NAIL RIGHT SIDE CENTER

50" D. FIR S50°E 47.0 FT (REC S57°E
70 LBS) FULLY HEATED SINGLE BLAZE
ADD 3 1/2" MAG NAIL RIGHT SIDE CENTER

RENEWAL

Monument Set (Procedure and Description)

MONUMENT DETAIL

2 1/2" Alum Cap on 5/8" x 30" Iron Rod proj 4" on West Edge of Rd pipe plum Position

DOUGLAS COUNTY

T325 R9W

1/4 S15
S22

2025

SURVEYORS OFFICE

New Accessories

1917 BRASS CAP AND BROKEN IRON pipe set on North edge of New Monument

13" D. FIR N16°E 25.0 FT Scribed 1/4 S15 BT ON Double BLAZE 3 1/2" MAG NAIL RIGHT SIDE Center

15" D. FIR S34°W 8.5 FT Scribed 1/4 S22 BT ON Double BLAZE 3 1/2" MAG NAIL RIGHT Side Center

Sketch of Monument, Accessories, and General Area

Location & Comments

Mon. on moderate East slope in older Reprod

MON IS 250 ± FT EAST OF GRAVEL ROAD

Trimble Geo XT position

42° 46' 58.483" N

123° 44' 45.480" W

Comp. Decline. 14 1/2° E

Agency DCSO

Party Chief S. E. Hase

Note keeper

Witnesses J. Loring

REGISTERED PROFESSIONAL LAND SURVEYOR

Ronald A. Quimby

OREGON JULY 14, 1978 RONALD A. QUIMBY 1654

EXPIRES: 12/31/2026

CS 67160-43

pg 2/3

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 15 & 22

Alias	Description
Alias	Description <u>TRIMBLE GEO & T POSITION</u>
Alias	Description
Alias	Description <u>42° 46' 58.483" N</u>
Alias	Description <u>123° 44' 45.480" W</u>

MINI GIS
42.78293
123.74593

GLO Dependent survey by Fred Mensch & Gerald A. Sorrels, Dep. Surveyors under special instructions dated Dec. 22, 1916 - (DCSO records Vol. 21 Page(s) 8898)

RENEWED 6/9/25

Set an iron post, 3 ft. long, 1" dia., 26" in the ground, for 1/4 sec. cor., with brass cap marked

DECLINATION 14 1/2° E

2 1/2" BC S 15 1917
S 22 REST OF 1" O.D. I.P. NEAR PLUMB IN GROUND

from which
35" AD Fir, 16" dia., bears N. 39° E., 89 lks., mkd: 1/4 S15 BT. FHSB BOTH BT.
50" AD Fir, 40" dia., bears S. 57° E., 70 lks., mkd: 1/4 S22 BT. FHSB

SET: 2 1/2" ALUM. CAP
ON 5/8" x 30" IRON ROD
SET ON WEST EDGE OF
FOUND I.P. = FOUND PIPE'S
PLUMB POSITION

ALUM. CAP "DOUGLAS COUNTY"
MARKED T32SR9W
S15
1/4 S22
2025
SURVEYOR'S OFFICE

PROT 4"
1917 B.C. AND BROKEN PIPE
SET ON NORTH EDGE OF NEW
MONUMENT, TOP FLUSH WITH
GROUND.

NEW REFERENCES:

A 13" DIA. D. FIR SCRIBED "1/4 S15" "BT" ON DOUBLE BLZ. BEARS N16° E, 25° FT.

A 18" DIA. D. FIR SCRIBED "1/4 S22" "BT" ON DOUBLE BLZ. BEARS S34° W, 85° FT.

BOTH NEW BTs HAVE 3 1/2" MAG NAIL R.S.C.

Mon. ON MODERATE EAST SLOPE IN OLD REGROWTH
~250 FT. EAST OF A GRAVEL RD.