

GOVERNMENT CORNER RESTORATION FORM

FILED

TOWNSHIP 27S RANGE 2W SEC. 1

PLSS # 400700

Date: 7/8/25 By: KL
This survey consists of:

Map: _____

DOUGLAS COUNTY OREGON

DATE 8-31-20

Narrative: _____

Corner Rpt: CS 67/60-49

Corner Designation

Sec Cor

S35/S36
S1/S2

DOUGLAS COUNTY
SURVEYOR

Monument(s) Found: (Condition and Source)

2 1/2" DC SO BRASS CAP

Condition report

Not Found

Renewed

Unrecorded

Surveyed In

Previous Renewals

GLD 1916 Vol 10 pg 4288

DC SO 1967 CS 54/40-5

BLM Resurvey 1979 Vol 43

pgs 16916-17

Geisler 1984 M 90-55

BLM Resurvey 1992-1995 Vol

51 pgs 1993-44

EDWARDS 2008 M 155-16

Accessories Found

MONUMENT DETAIL

COUNTY SURVEYORS
OFFICE

T26S S35/S36 R2W
T27S S1
1967

27" FIR S30°W 15.8FT (Rec 24 LKS)

30" FIR N39 1/2°E 11.9 FT (Rec 18 LKS)

21" FIR N3 1/2°E 5.3 FT (Rec 8 LKS)

23" FIR S84°E 87.1 FT (Rec 132 LKS)

30" FIR S13°W 19.8 FT (Rec 30 LKS)

GOVERNMENT CORNER RESTORATION FORM

FILED

TOWNSHIP _____ RANGE _____ SEC. _____ PLSS # _____

Date: _____ By: _____

This survey consists of: _____

Map: _____

Narrative: _____

Corner Rpt: _____

DOUGLAS COUNTY OREGON

DATE _____

DOUGLAS COUNTY
SURVEYOR

Corner Designation

Monument(s) Found: (Condition and Source)

Condition report

Not Found

Renewed

Unrecorded

Surveyed In

Previous Renewals

MONUMENT DETAIL

Accessories Found

FIND OK
8/31/20

TOWNSHIP 27 RANGE 02 POINT IDENTIFIER # 600700

PRIMARY CORNER DESCRIPTION Sec. Cor. for 1 & 2; 35 & 36, T26-2

NEW
TREE
SIZES
SEE PG 2

Alias_____	Description_____
Alias_____	Description_____
Alias_____	Description_____
Alias_____	Description_____

GLO survey by S.C. Flint, Contract #459, dated August 3, 1882
- (DCSO records Vol. 10 Page(s) 4185)

Set Laurel post 4 ft. long, 4" sq., 24" in the ground for cor. to secs. 1, 2, 35 and 36, mkd. T26S S36 on NE.; R2W S1 on SE.; T27S S2 on SW.; S35 on NW. faces, with 1 notch on E. and 5 notches on W. edges, from which

A Laurel 8" dia., bears N.55°E., 30 lks. dist. mkd. T26S R2W S36 BT.

A Laurel 10" dia., bears S.70°E., 30 lks. dist. mkd. T27S R2W S1 BT.

A Fir 12" dia., bears S.30°W., 24 lks. mkd. T27S R2W S2 BT

A Fir 12" dia. bears N.14°W., 14 lks. mkd. T26S R2W S35 BT

GLO Survey by Fred Mensch, U.S. Surveyor Under Special Instructions dated May 25, 1916 - (DCSO records Vol. 10 Page(s) 4288)

Intersect the cor. of secs. 1, 2, 35 and 36, established by Deputy Flint in 1882 and reestablished by U.S. Surveyor Collier in 1913, which is a basalt stone, 5x8x7 ins. above ground, firmly set, marked with 1 notch on E. and 5 notches on W. edge, from which

A Fir 10" dia., bears N.39°30'E., 18 lks. dist. mkd. T26S R2W S36 BT.

A Laurel 10" dia., bears S.70°E., 30 lks. dist. mkd. T27S R2W S1 BT. (Orig. BT)

A Fir 20" dia., bears S.30°W., 24 lks. dist. mkd. T27S R2W S2 BT. (orig. BT)

The original bearing tree on NW., a Fir 20" dia., which bears from the cor. N.14°W., 14 lks. dist., is not in the section to which it refers; therefore, I obliterate marks on this tree and take new bearing tree in sec. 35 as follows:

A Fir 24" dia., bears N.30°W., 52 lks. dist. mkd. T26S R2W S35 BT.

(Note: At this point in time (July 27, 1997) in the material furnished me, I cannot find a Collier 1913 survey description for this corner. V.Laugen)

Douglas County Surveyors Office - Vernon "Ray" Tracy and crew
March 9, 1967 - C.S. File 54/40-5

Found - No trace of corner stone.
Orig. 12" now 21" Fir, alive, S.30°W., 15.8 ft., previously opened, face burned, fragmentary scribe visible.

(Cont. Next Page)

CS 67/60-49
pg 3/4

4

TOWNSHIP 27 RANGE 02 POINT IDENTIFIER # 600700

PRIMARY CORNER DESCRIPTION Sec. Cor. for 1 & 2; 35 & 36, T26-2

Alias_____	Description_____
Alias_____	Description_____
Alias_____	Description_____
Alias_____	Description_____

Orig. 10" now 19" Fir, alive, N.39½°E., 11.9 ft., previously opened. Open all of upper blaze and find "T26S R2W S36" scribe.

Orig. 24" now 30" Fir, alive, N.30°W., 34.3 ft., shows good scar.

Orig. BT, N.11°W., 9.2 ft., obliterated by Mensch in 1916, alive, and opened to axe blaze.

Set Brass cap at cor. mkd: County Surveyors Office

T 26 S	S 35	S 36	
T 27 S	2	S 1	R2W

1967

New BTs- 16" D.Fir S.79½°E., 88.7 ft. mkd. T27S R2W S1 CS BT.
 14" D.Fir N.4°E., 6.0 ft. mkd. T26S R2W S36 CS BT.
 18" D.Fir S.19°W., 19.7 ft. mkd. T27S R2W S2 CS BT.
 No trace of any other original BTs.

Fd. and used in BLM Resurvey by Wayne L. Rogers, Cadastral Surveyor, under Group #983, Surveyed May/Aug. 1979 - (DCSO records Vol. 43 Page(s) 16916-17)

Fd. OK, April 1984 by R. Geisler - M 90-55

BLM dependent resurvey by Dale T. Bedell & Bryan S. Seibold, Cadastral Surveyors & Robert H. Browning, Survey Technician, under Group No. 1638, surveyed July 1992/April 1995 - (DCSO records Vol. 51 (Page(s) 19743-4)

The cor. of secs. 1, 2, 35 and 36, on the S. bdy. of the Tp., perpetuated by Tracy, in 1967, monumented with an iron post, 1" dia., firmly set, projecting 5" above the ground, with brass cap (properly) mkd.

from which the remains of the original bearing trees

27" A fir, 25" dia., bears S.30°W., 24 lks., with a healed blaze.

A fir stump, 22" dia., bears N.14°W., 14 lks., with a healed blaze.

and a BT mkd. by Collier in 1913, and reported by Mensch

30" A fir, 25" dia. bears N.39½°E. 18 lks. with decayed blaze and bearing trees mkd. by Tracy

21" A fir, 17" dia. bears N.3½°E. 8 lks. with healed dbl blaze

22" A fir, 19" dia bears S.84°E. 132 lks with healed dbl blaze

30" A fir, 27" dia. bears S.13°W. 30 lks with healed dbl blaze

No suitable bearing trees available NW. of the corner.

Fd. BC & 5 BTs by D. Edwards, 3/2008 - M155-16

CS 67160-49

pg 4/4